This item was submitted to Loughborough's Research Repository by the author.
Items in Figshare are protected by copyright, with all rights reserved, unless otherwise indicated.

SaferWheels study on powered two-wheeler and bicycle accidents in the EU - Annex 6 case summaries

PLEASE CITE THE PUBLISHED VERSION

https://doi.org/10.2832/34740

PUBLISHER

© European Union

VERSION

VoR (Version of Record)

PUBLISHER STATEMENT

This work is made available according to the conditions of the Creative Commons Attribution-NonCommercial-NoDerivatives 4.0 International (CC BY-NC-ND 4.0) licence. Full details of this licence are available at: https://creativecommons.org/licenses/by-nc-nd/4.0/

LICENCE

CC BY-NC-ND 4.0

REPOSITORY RECORD

Morris, Andrew, Laurie Brown, Pete Thomas, R.J. Davidse, V. Phan, Dimitris Margaritis, D. Shingo Usami, M. Robibaro, A. Krupinska, and K. Sicinska. 2019. “Saferwheels Study on Powered Two-wheeler and Bicycle Accidents in the EU - Annex 6 Case Summaries”. figshare. https://hdl.handle.net/2134/36175.

Reporting Date: July 2018
Version: Final

European Commission

Contract no. MOVE/C4/2014-661-2

SAFERWHEELS

Study on Powered Two-Wheeler and Bicycle Accidents in the EU

Annex 6 - Case Summaries

Prepared by:

A.P. Morris, L.A. Brown, P. Thomas	Loughborough University, UK
R.J. Davidse	SWOV, The Netherlands
V. Phan	CEESAR, France
D. Margaritis	CERTH, Greece
D. Usami, M. Robibaro	CTL, Italy
A. Krupińska, K. Sicińska	ITS, Poland

July 2018

Disclaimer

The case summaries contained within this document form an Annex and should be viewed with respect to the SaferWheels final study report, which is available from the European Commission.

The information and views set out in this study are those of the author(s) and do not necessarily reflect the official opinion of the Commission. The Commission does not guarantee the accuracy of the data included in this study. Neither the Commission nor any person acting on the Commission's behalf may be held responsible for the use which may be made of the information contained therein.

EUROPEAN COMMISSION

Directorate-General for Mobility and Transport

Directorate C — Land

Unit C2 — Road Safety

E-mail:MOVE-C2-SECRETARIAT@ec.europa.eu

European Commission

B-1049 Brussels

Europe Direct is a service to help you find answers to your questions about the European Union. Freephone number (*):

00 800 6 7 8 9 10 11

(*) The information given is free, as are most calls (though some operators, phone boxes or hotels may charge you).

LEGAL NOTICE

This document has been prepared for the European Commission however it reflects the views only of the authors, and the Commission cannot be held responsible for any use which may be made of the information contained therein.

More information on the European Union is available on the Internet (http://www.europa.eu).

Luxembourg: Publications Office of the European Union, 2018

ISBN 978-92-79-90392-2

doi: 10.2832/34740

© European Union, 2018

Reproduction is authorised provided the source is acknowledged.

SaferWheels Study - CASE CEE1

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Darkness
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.1	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		billboard	

SaferWheels Study - CASE CEE2

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Wednesday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	Y-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	1	0	0
Max Severity	Slight	-	-	Not injured	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		signs	

SaferWheels Study - CASE CEE3

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	732	others - moving obstacle - others
CADAS accident type 1:	A-10.05	A-10.05 Single vehicle accidents with obstacles - others
CADAS accident type 2:	A-8.08	A-8.08 Pedestrian accident - other
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	Heavy	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.23	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	maintenance zone
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE4

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Thursday		**Area classification:**	Urban		
Season:	Winter		**Accident environment:**	Industrial		
Year:	2016		**Animal involvement?**	No		
Time band:	05:00-08:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	632	Longitudinal Traffic - lane change to the left because of congestion and follower
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	110	**Vertical geometry at location:**	Level
Road width (m):	7.4	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE CEE5

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	0		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	00:00-04:59		**Alcohol involvement?**		Suspected	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	601	Longitudinal traffic ? veh. and follower 1st lane
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	Unknown

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	70	**Vertical geometry at location:**	Level
Road width (m):	6.2	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Unknown
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE6

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	601	Longitudinal traffic ? veh. and follower 1st lane
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6.98	**Bend direction at location:**	Bend right
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE CEE7

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	642	Longitudinal Traffic - lane change to the right because of congestion and follower
CADAS accident type 1:	-	-
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	110	**Vertical geometry at location:**	Level
Road width (m):	10.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	-	**Special lane type:**	Yes
Road barrier present?	-	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	-	**Signage contributed to accident?**	No
Road surface defects:	-	**Road surface contaminants?**	-
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE8

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Other	
Year:	2015		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	1	0	0
Max Severity	Fatal	-	-	Not injured	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	-	-
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	110	**Vertical geometry at location:**	Level
Road width (m):	10.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study – CASE CEE10

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	232	Turning of accident - following veh. besides right turning veh.
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	70	**Vertical geometry at location:**	Level
Road width (m):	6.15	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE11

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Saturday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	153	Driving accident- gradient, straight road
CADAS accident type 1:	A-10.08	A-10.08 Single vehicle accidents on the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	90	**Vertical geometry at location:**	Unknown
Road width (m):	12	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE12

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Industrial	
Year:	2015		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Unknown	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	-	-
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	-
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE CEE13

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Thursday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Other	
Year:	2015		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	631	Longitudinal Traffic - lane change to the left because of veh. ahead and follower
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Not applicable
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE14

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE15

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	571	Resting Traffic - parking out backward from perpendicular position on the right
CADAS accident type 1:	-	-
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	11.6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Damp	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE CEE16

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Unknown	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	roundabout		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	101	Driving accident- left turn
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Left
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.68	**Bend direction at location:**	Bend left
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE17

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Unknown	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	101	Driving accident- left turn
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	-	**Vertical geometry at location:**	Level
Road width (m):	5.2	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE18

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	roundabout		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	353	crossing - turning priority road and veh. from the left
CADAS accident type 1:	AA-12.52	AA-12.52 At least two vehicles - turning or crossing - same road - opposite direction - not specified
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.1	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE19

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Monday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	721	Others - veh. turning around and traffic from behind
CADAS accident type 1:	A-12.02	A-12.02 At least two vehicles - turning - same road - same direction - U-turn in front of other vehicle
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.65	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE20

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Yes	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	621	Longitudinal Traffic - veh. waiting mendatory and follower
CADAS accident type 1:	A-12.01	A-12.01 At least two vehicles - turning - same road - same direction - rear end collision
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up slight
Road width (m):	5.6	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE21

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Friday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	05:00-08:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	621	Longitudinal Traffic - veh. waiting mendatory and follower
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	10.1	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	Not applicable	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE22

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Other		
Year:	2016		**Animal involvement?**	No		
Time band:	05:00-08:59		**Alcohol involvement?**	No		
Junction type:	roundabout		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	223	Turning of accident - left turning veh. and cyclist from bicycle lane in same direction
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	9.43	**Bend direction at location:**	Bend left
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE23

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	A-10.06	A-10.06 Single vehicle accident - Leaving straight road - either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5.53	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE24

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Sunday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	271	Turning of accident - veh. from right turning priority road and other vehicle
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Other
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	90	**Vertical geometry at location:**	Level
Road width (m):	5.9	**Bend direction at location:**	Other
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE25

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	-Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	601	Longitudinal traffic ? veh. and follower 1st lane
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	90	**Vertical geometry at location:**	Level
Road width (m):	9.14	**Bend direction at location:**	Bend right
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Unknown	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		atmospheric conditions	

SaferWheels Study - CASE CEE26

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	roundabout		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	162	Driving accident- traffic island and right turn
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Darkness
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Right light
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.53	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE27

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	763	others - other disability without alcohol
CADAS accident type 1:	A-10.06	A-10.06 Single vehicle accident - Leaving straight road - either side of the road
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5.05	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE28

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	132	Driving accident- non-straight street, bending to the right
CADAS accident type 1:	A-10.09	A-10.09 Single vehicle accidents including rollover
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	70	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Bend right
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE29

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Saturday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	1	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	681	Longitudinal Traffic - encountering vehicles on roadway
CADAS accident type 1:	A-11.06	A-11.06 At least two vehicles - head on collision in general
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down
Road width (m):	4.97	**Bend direction at location:**	Bend right
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE30

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down
Road width (m):	7.37	**Bend direction at location:**	Bend left
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		urban furniture	

SaferWheels Study - CASE CEE31

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Residential		
Year:	2015		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	753	others - animal on roadway - pet with supervision
CADAS accident type 1:	-	-
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10.94	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE32

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	773	others - sudden technical failure - brakes
CADAS accident type 1:	A-10.05	A-10.05 Single vehicle accidents with obstacles - others
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Not applicable
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	4.75	**Bend direction at location:**	Bend right
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE CEE33

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	251	Turning of accident - two veh. turning left
CADAS accident type 1:	A-12.05	A-12.05 At least two vehicles - turning - same road - same direction - others
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	11.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE34

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	132	Driving accident- non-straight street, bending to the right
CADAS accident type 1:	A-10.06	A-10.06 Single vehicle accident - Leaving straight road - either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	70	**Vertical geometry at location:**	Down slight
Road width (m):	5.7	**Bend direction at location:**	Bend right
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Unknown	

SaferWheels Study - CASE CEE35

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Other	
Year:	2015		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	631	Longitudinal Traffic - lane change to the left because of veh. ahead and follower
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Not applicable
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	110	**Vertical geometry at location:**	Level
Road width (m):	10.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE36

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		Yes	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Not injured	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	452	Pedestrian crossing - from the right before intersection - while overtaking
CADAS accident type 1:	A-8.02	A-8.02 Pedestrian crossing street - no turning of vehicle - at a junction
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Not applicable
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	-
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	9	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE CEE37

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Wednesday		**Area classification:**	Rural		
Season:	Winter		**Accident environment:**	Other		
Year:	2016		**Animal involvement?**	No		
Time band:	17:00-19:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Darkness
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	70	**Vertical geometry at location:**	Level
Road width (m):	6.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE38

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Industrial		
Year:	2016		**Animal involvement?**	No		
Time band:	20:00-23:59		**Alcohol involvement?**	No		
Junction type:	roundabout		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	101	Driving accident- left turn
CADAS accident type 1:	A-10.08	A-10.08 Single vehicle accidents on the road
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Darkness
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	9.18	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE39

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Wednesday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Not applicable
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	70	**Vertical geometry at location:**	Level
Road width (m):	6.6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE40

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	1	0	0
Max Severity	Slight	-	-	Not injured	-	-

Collision Scenario		
DaCoTA accident type:	681	Longitudinal Traffic - encountering vehicles on roadway
CADAS accident type 1:	A-11.06	A-11.06 At least two vehicles - head on collision in general
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	4.6	**Bend direction at location:**	Bend right
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE41

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	05:00-08:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Slight	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up slight
Road width (m):	5	**Bend direction at location:**	Other
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Parked vehicles	

SaferWheels Study - CASE CEE42

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Saturday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Not injured	-	Slight	-	-	-

Collision Scenario		
DaCoTA accident type:	661	Longitudinal Traffic - overtaking veh. and oncoming traffic
CADAS accident type 1:	A-8.00	A-8.00 Not applicable
CADAS accident type 2:	AA-11.52	AA-11.52 At least two vehicles - opposite direction no turning - not specified
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Darkness
Snowfall:	No	**Cloud cover:**	Not applicable
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	70	**Vertical geometry at location:**	Level
Road width (m):	6.4	**Bend direction at location:**	Bend left
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE43

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	-	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	646	Longitudinal Traffic - lane change to the right after passing on parallel lane and follower
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Darkness
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	90	**Vertical geometry at location:**	Level
Road width (m):	20.67	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Not applicable
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE44

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Friday		**Area classification:**	Rural		
Season:	Spring		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	721	Others - veh. turning around and traffic from behind
CADAS accident type 1:	A-12.02	A-12.02 At least two vehicles - turning - same road - same direction - U-turn in front of other vehicle
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	4.5	**Bend direction at location:**	Bend left
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE45

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Industrial	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	632	Longitudinal Traffic - lane change to the left because of congestion and follower
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	110	**Vertical geometry at location:**	Level
Road width (m):	7.4	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE CEE46

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	AA-12.52	AA-12.52 At least two vehicles - turning or crossing - same road - opposite direction - not specified
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Not applicable
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	60.3	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Unknown
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		vegetation, embankment	

SaferWheels Study - CASE CEE47

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Monday		**Area classification:**	Rural		
Season:	Spring		**Accident environment:**	Other		
Year:	2016		**Animal involvement?**	No		
Time band:	05:00-08:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	70	**Vertical geometry at location:**	Level
Road width (m):	5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	0	**Special lane type:**	No
Road barrier present?	0	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	0	**Signage contributed to accident?**	No
Road surface defects:	0	**Road surface contaminants?**	0
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE48

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Thursday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Industrial	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	101	Driving accident- left turn
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Bend left
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE49

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	slip road/ ramp		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	611	Longitudinal Traffic - congestion and follower 1st lane
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	110	**Vertical geometry at location:**	Up slight
Road width (m):	16.5	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE50

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	601	Longitudinal traffic ? veh. and follower 1st lane
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.04	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE51

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.04	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Damp	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE52

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Tuesday		**Area classification:**	Rural		
Season:	Spring		**Accident environment:**	Other		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	643	Longitudinal Traffic - lane change to the right because of ending lane and follower
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	110	**Vertical geometry at location:**	Level
Road width (m):	10	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE53

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	1	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.10	A-12.10 At least two vehicles - same road - opposite direction - turning right (left) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE54

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Thursday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	roundabout		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	351	crossing - turning priority road and oncoming traffic straight ahead
CADAS accident type 1:	A-12.08	A-12.08 At least two vehicles - same road - opposite direction - turning into same road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	10	**Bend direction at location:**	Bend left
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Other	

SaferWheels Study - CASE CEE55

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	0	0	0	0
Max Severity	-	Slight	-	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	A-10.06	A-10.06 Single vehicle accident - Leaving straight road - either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	11.64	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE56

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Monday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	0	1	0	0
Max Severity	-	Fatal	-	Not injured	-	-

Collision Scenario		
DaCoTA accident type:	343	crossing - bicycle with right of way from oncoming bicycle lane left and straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	14.9	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		vegetation, embankment	

SaferWheels Study – CASE CEE57

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Winter		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.14	A-12.14 At least two vehicles - different roads - turning right (left) - head on collision
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	6.51	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Parked vehicles	

SaferWheels Study - CASE CEE58

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Wednesday		**Area classification:**	Rural		
Season:	Winter		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	05:00-08:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	1	0	0
Max Severity	Serious	-	-	Not injured	-	-

Collision Scenario		
DaCoTA accident type:	562	Resting Traffic - parking out forward from perpendicular position on the left
CADAS accident type 1:	A-12.14	A-12.14 At least two vehicles - different roads - turning right (left) - head on collision
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.1	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE59

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		Yes	
Junction type:	crossroads		**Drug involvement?**		Yes	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	452	Pedestrian crossing - from the right before intersection - while overtaking
CADAS accident type 1:	A-8.02	A-8.02 Pedestrian crossing street - no turning of vehicle - at a junction
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6.1	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE60

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		Yes	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Not injured	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	452	Pedestrian crossing - from the right before intersection - while overtaking
CADAS accident type 1:	A-8.02	A-8.02 Pedestrian crossing street - no turning of vehicle - at a junction
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up slight
Road width (m):	7.3	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE61

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	6.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE62

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	281	Turning of accident - veh. turning left with green arrow light and oncoming traffic ahead
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Not applicable
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	11	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Not applicable
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE63

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Monday		**Area classification:**	Rural		
Season:	Winter		**Accident environment:**	Other		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	1	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	601	Longitudinal traffic ? veh. and follower 1st lane
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	-	**Cloud cover:**	Not applicable
Fog/Mist:	-	**Strong wind:**	-

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	110	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE64

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Not applicable
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		walls / dwellings	

SaferWheels Study - CASE CEE65

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Tuesday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	1	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	646	Longitudinal Traffic - lane change to the right after passing on parallel lane and follower
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Not applicable
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	110	**Vertical geometry at location:**	Level
Road width (m):	7.4	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE66

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	A-10.06	A-10.06 Single vehicle accident - Leaving straight road - either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	5.5	**Bend direction at location:**	Not Applicable
Camber:	Negative	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Unknown	

SaferWheels Study - CASE CEE67

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Thursday		**Area classification:**	Rural		
Season:	Autumn		**Accident environment:**	Other		
Year:	2016		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	slip road/ ramp		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	102	Driving accident- right turn
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Not applicable
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6.8	**Bend direction at location:**	Bend right
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	oil
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Other	

SaferWheels Study - CASE CEE68

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Industrial	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	1	0	0
Max Severity	Fatal	-	-	Not injured	-	-

Collision Scenario		
DaCoTA accident type:	646	Longitudinal Traffic - lane change to the right after passing on parallel lane and follower
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	-	**Light Condition:**	-
Snowfall:	-	**Cloud cover:**	-
Fog/Mist:	-	**Strong wind:**	-

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	90	**Vertical geometry at location:**	Level
Road width (m):	8.7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE69

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Friday		**Area classification:**	Rural		
Season:	Summer		**Accident environment:**	Other		
Year:	2016		**Animal involvement?**	No		
Time band:	05:00-08:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	646	Longitudinal Traffic - lane change to the right after passing on parallel lane and follower
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Not applicable
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	110	**Vertical geometry at location:**	Level
Road width (m):	9.1	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE70

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	322	crossing - veh. with right of way from right and turning left
CADAS accident type 1:	A-12.13	A-12.13 At least two vehicles - different roads - turning right (left) in front of vehicle from the left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5.5	**Bend direction at location:**	Bend right
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE71

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	542	Resting Traffic - stopping/parking same direction to the left
CADAS accident type 1:	AA-12.51	AA-12.51 At least two vehicles - turning - same road - same direction - not specified
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Not applicable
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE72

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	1
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	542	Resting Traffic - stopping/parking same direction to the left
CADAS accident type 1:	AA-12.51	AA-12.51 At least two vehicles - turning - same road - same direction - not specified
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	Light	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Right light
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	6.8	**Bend direction at location:**	Not Applicable
Camber:	Negative	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE73

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	05:00-08:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	-	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	561	Resting Traffic - parking out forward from perpendicular position on the right
CADAS accident type 1:	A-12.14	A-12.14 At least two vehicles - different roads - turning right (left) - head on collision
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	Not applicable	**Vertical geometry at location:**	Level
Road width (m):	5.8	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	0	**Special lane type:**	No
Road barrier present?	0	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	0	**Signage contributed to accident?**	No
Road surface defects:	0	**Road surface contaminants?**	0
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		walls / dwellings	

SaferWheels Study - CASE CEE74

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Tuesday		**Area classification:**	Rural		
Season:	Autumn		**Accident environment:**	Industrial		
Year:	2016		**Animal involvement?**	No		
Time band:	05:00-08:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	631	Longitudinal Traffic - lane change to the left because of veh. ahead and follower
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	90	**Vertical geometry at location:**	Level
Road width (m):	10.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE CEE75

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Wednesday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	721	Others - veh. turning around and traffic from behind
CADAS accident type 1:	A-12.02	A-12.02 At least two vehicles - turning - same road - same direction - U-turn in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	70	**Vertical geometry at location:**	Level
Road width (m):	7.2	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE76

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	661	Longitudinal Traffic - overtaking veh. and oncoming traffic
CADAS accident type 1:	AA-11.51	AA-11.51 At least two vehicles - same direction no turning - not specified
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	5.2	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	potholes	**Road surface contaminants?**	gravel
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE77

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Thursday		**Area classification:**	Rural		
Season:	Winter		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	05:00-08:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.14	A-12.14 At least two vehicles - different roads - turning right (left) - head on collision
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6.9	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	0	**Special lane type:**	0
Road barrier present?	0	**Barrier collided with?**	0
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	0	**Signage contributed to accident?**	No
Road surface defects:	0	**Road surface contaminants?**	0
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE CEE78

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Tuesday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	401	Pedestrian crossing from left onto roadway without obstacle
CADAS accident type 1:	A-8.01	A-8.01 Pedestrian crossing street - no turning of vehicle - outside a junction
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	6.9	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE79

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Sunday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2014		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Not applicable
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	90	**Vertical geometry at location:**	Level
Road width (m):	5.66	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	mud
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE80

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		France	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Not applicable	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	631	Longitudinal Traffic - lane change to the left because of veh. ahead and follower
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Darkness
Snowfall:	Heavy	**Cloud cover:**	Total
Fog/Mist:	Light	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	110	**Vertical geometry at location:**	Level
Road width (m):	10.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE81

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	601	Longitudinal traffic ? veh. and follower 1st lane
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Not applicable
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	110	**Vertical geometry at location:**	Level
Road width (m):	3	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	maintenance zone
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE82

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Monday		**Area classification:**	Urban		
Season:	Winter		**Accident environment:**	Residential		
Year:	2015		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	roundabout		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	303	crossing - veh. with right of way from left and turning right
CADAS accident type 1:	A-12.13	A-12.13 At least two vehicles - different roads - turning right (left) in front of vehicle from the left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Other	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	30	**Vertical geometry at location:**	Not applicable
Road width (m):	9	**Bend direction at location:**	Bend right
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE83

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	433	Pedestrian crossing - from the left, before intersection without obstacle - while passing
CADAS accident type 1:	A-8.02	A-8.02 Pedestrian crossing street - no turning of vehicle - at a junction
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	12	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE84

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Tuesday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	682	Longitudinal Traffic - encountering vehicles in curve
CADAS accident type 1:	A-11.06	A-11.06 At least two vehicles - head on collision in general
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5.8	**Bend direction at location:**	Bend left
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE85

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	A-10.06	A-10.06 Single vehicle accident - Leaving straight road - either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	90	**Vertical geometry at location:**	Level
Road width (m):	10	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE86

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		France	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Not applicable	
Year:	2015		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	721	Others - veh. turning around and traffic from behind
CADAS accident type 1:	A-12.02	A-12.02 At least two vehicles - turning - same road - same direction - U-turn in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Not applicable
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	70	**Vertical geometry at location:**	Level
Road width (m):	7.8	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CEE87

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	France		
Day of the week:	Thursday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Not applicable		
Year:	2016		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	roundabout		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	651	Longitudinal Traffic - parallel driving in same direction
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Right sharp
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	25	**Bend direction at location:**	Bend left
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Damp	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER1

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Greece		
Day of the week:	Sunday		**Area classification:**	Rural		
Season:	Spring		**Accident environment:**	Residential		
Year:	2015		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	2	0	0	0
Max Severity	Fatal	-	N/A	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Parked vehicles	

SaferWheels Study - CASE CER2

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Greece		
Day of the week:	Thursday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Residential		
Year:	2015		**Animal involvement?**	No		
Time band:	05:00-08:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	2	0	0	0
Max Severity	Fatal	-	Slight	-	-	-

Collision Scenario		
DaCoTA accident type:	681	Longitudinal Traffic - encountering vehicles on roadway
CADAS accident type 1:	A-11.06	A-11.06 At least two vehicles - head on collision in general
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Not applicable
Road width (m):	8	**Bend direction at location:**	Not Applicable
Camber:	Not applicable	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER3

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Greece		
Day of the week:	Sunday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	17:00-19:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	601	Longitudinal traffic ? veh. and follower 1st lane
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	90	**Vertical geometry at location:**	Level
Road width (m):	6.2	**Bend direction at location:**	Not Applicable
Camber:	Not applicable	**Construction / maintenance zone?**	construction zone
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	Yes
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER4

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Greece		
Day of the week:	Monday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	20:00-23:59		**Alcohol involvement?**	Yes		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	461	Pedestrian crossing - from the left behind intersection
CADAS accident type 1:	A-8.01	A-8.01 Pedestrian crossing street - no turning of vehicle - outside a junction
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	90	**Vertical geometry at location:**	Level
Road width (m):	12.9	**Bend direction at location:**	Not Applicable
Camber:	Not applicable	**Construction / maintenance zone?**	construction zone
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER5

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Greece		
Day of the week:	Tuesday		**Area classification:**	Rural		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	0	0	0	1
Max Severity	-	Fatal	-	-	-	Not injured

Collision Scenario		
DaCoTA accident type:	363	crossing - guarded railway crossing on intersection
CADAS accident type 1:	A-10.04	A-10.04 Accidents between train and vehicle
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vegetation, embankment	

SaferWheels Study - CASE CER6

Short Summary (not restricted)

Overview Details						
Investigation type:	-		**Country of investigation:**		Greece	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	681	Longitudinal Traffic - encountering vehicles on roadway
CADAS accident type 1:	A-12.10	A-12.10 At least two vehicles - same road - opposite direction - turning right (left) in front of other vehicle
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	21	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER7

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Wednesday		**Area classification:**	Rural		
Season:	Autumn		**Accident environment:**	Residential		
Year:	2015		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	A-9.02	A-9.02 Hitting parked vehicles left (right) side of the road
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	3	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER8

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Sunday		**Area classification:**		Rural	
Season:	Winter		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	12	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER9

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Greece		
Day of the week:	Thursday		**Area classification:**	Urban		
Season:	Winter		**Accident environment:**	Residential		
Year:	2015		**Animal involvement?**	No		
Time band:	17:00-19:59		**Alcohol involvement?**	Yes		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	102	Driving accident- right turn
CADAS accident type 1:	A-10.08	A-10.08 Single vehicle accidents on the road
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	14	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER10

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Not injured	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	421	Pedestrian crossing - from the right onto roadway
CADAS accident type 1:	A-8.02	A-8.02 Pedestrian crossing street - no turning of vehicle - at a junction
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	14	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER11

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Wednesday		**Area classification:**		Rural	
Season:	Winter		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	3	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Possibly (give details and take photos)
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Parked vehicles	

SaferWheels Study - CASE CER12

Short Summary (not restricted)

Overview Details						
Investigation type:	-		**Country of investigation:**		Greece	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	681	Longitudinal Traffic - encountering vehicles on roadway
CADAS accident type 1:	A-11.06	A-11.06 At least two vehicles - head on collision in general
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up slight
Road width (m):	8	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	thin ice	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER13

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	1
Max Severity	Not injured	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	421	Pedestrian crossing - from the right onto roadway
CADAS accident type 1:	A-8.01	A-8.01 Pedestrian crossing street - no turning of vehicle - outside a junction
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER14

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	643	Longitudinal Traffic - lane change to the right because of ending lane and follower
CADAS accident type 1:	A-12.07	A-12.07 At least two vehicles - same road - opposite direction - U-turn in front of other vehicle
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	21	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER15

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	2	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	232	Turning of accident - following veh. besides right turning veh.
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	19	**Bend direction at location:**	Not Applicable
Camber:	Not applicable	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER17

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Greece	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	101	Driving accident- left turn
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Left
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8	**Bend direction at location:**	Not Applicable
Camber:	Not applicable	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Unknown	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	Unknown
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER18

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER19

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Saturday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	542	Resting Traffic - stopping/parking same direction to the left
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	19.8	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER20

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Yes	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	763	others - other disability without alcohol
CADAS accident type 1:	A-10.06	A-10.06 Single vehicle accident - Leaving straight road - either side of the road
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER21

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	282	Turning of accident - veh. turning left with green arrow light and pedestrian
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	14	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER23

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Tuesday		**Area classification:**	Rural		
Season:	Spring		**Accident environment:**	Industrial		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	543	Resting Traffic - stopping/parking opposite direction to the left
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER24

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Wednesday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	721	Others - veh. turning around and traffic from behind
CADAS accident type 1:	A-12.02	A-12.02 At least two vehicles - turning - same road - same direction - U-turn in front of other vehicle
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	40	**Vertical geometry at location:**	Level
Road width (m):	17	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	yes	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		temporary cause	

SaferWheels Study - CASE CER25

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Friday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	17:00-19:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.14	A-12.14 At least two vehicles - different roads - turning right (left) - head on collision
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		temporary cause	

SaferWheels Study - CASE CER26

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	9	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER27

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Yes	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	421	Pedestrian crossing - from the right onto roadway
CADAS accident type 1:	A-8.02	A-8.02 Pedestrian crossing street - no turning of vehicle - at a junction
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	21	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER29

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	542	Resting Traffic - stopping/parking same direction to the left
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	15	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER30

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER31

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Thursday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	1	0	0
Max Severity	Slight	-	-	Not injured	-	-

Collision Scenario		
DaCoTA accident type:	623	Longitudinal Traffic - veh. waiting mendatory and follower before intersection or traffic light
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	20	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	yes	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER32

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Friday		**Area classification:**	Rural		
Season:	Spring		**Accident environment:**	Industrial		
Year:	2016		**Animal involvement?**	No		
Time band:	05:00-08:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	Light	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER33

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	601	Longitudinal traffic ? veh. and follower 1st lane
CADAS accident type 1:	AA-11.51	AA-11.51 At least two vehicles - same direction no turning - not specified
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	11	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE CER34

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Friday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	20:00-23:59		**Alcohol involvement?**	No		
Junction type:	Y-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	2	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	542	Resting Traffic - stopping/parking same direction to the left
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	40	**Vertical geometry at location:**	Down slight
Road width (m):	9	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER35

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	721	Others - veh. turning around and traffic from behind
CADAS accident type 1:	A-12.07	A-12.07 At least two vehicles - same road - opposite direction - U-turn in front of other vehicle
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	14	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER36

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Greece		
Day of the week:	Wednesday		**Area classification:**	Rural		
Season:	Spring		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	201	Turning of accident - following veh. behind left turning veh.
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER37

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Wednesday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	17:00-19:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	2	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	582	Resting Traffic - door getting in/out on the left
CADAS accident type 1:	A-8.00	A-8.00 Not applicable
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	24.3	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER38

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Thursday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	201	Turning of accident - following veh. behind left turning veh.
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER39

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Friday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	05:00-08:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6.3	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER40

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	232	Turning of accident - following veh. besides right turning veh.
CADAS accident type 1:	A-10.03	A-10.03 Single vehicle accidents with roadwork materials
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	16	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER41

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Greece		
Day of the week:	Tuesday		**Area classification:**	Rural		
Season:	Spring		**Accident environment:**	Industrial		
Year:	2016		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	542	Resting Traffic - stopping/parking same direction to the left
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	18	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER42

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6.6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER43

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		Yes	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	601	Longitudinal traffic ? veh. and follower 1st lane
CADAS accident type 1:	A-10.08	A-10.08 Single vehicle accidents on the road
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	9.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER45

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Sunday		**Area classification:**	Rural		
Season:	Spring		**Accident environment:**	Other		
Year:	2016		**Animal involvement?**	No		
Time band:	17:00-19:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	682	Longitudinal Traffic - encountering vehicles in curve
CADAS accident type 1:	A-11.08	A-11.08 At least two vehicles - opposite direction no turning - others
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	70	**Vertical geometry at location:**	Level
Road width (m):	8	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	maintenance zone
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Unknown	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER46

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Sunday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Yes	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	102	Driving accident- right turn
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Right light
Speed Limit (km/h):	90	**Vertical geometry at location:**	Down slight
Road width (m):	21	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER47

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Monday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	20:00-23:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	602	Longitudinal Traffic - veh. and follower 2nd lane
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	32	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER48

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up slight
Road width (m):	7.6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER49

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER51

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	17:00-19:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	3.2	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Unknown	
- Main cause of sight restrictions		Unknown	

SaferWheels Study - CASE CER52

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Saturday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	00:00-04:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	2	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	561	Resting Traffic - parking out forward from perpendicular position on the right
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	14	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER53

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Saturday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	00:00-04:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	3	0	0	0
Max Severity	Serious	-	Unknown	-	-	-

Collision Scenario		
DaCoTA accident type:	102	Driving accident- right turn
CADAS accident type 1:	A-9.01	A-9.01 Hitting parked vehicles right (left) side of the road
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	21	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER54

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.10	A-12.10 At least two vehicles - same road - opposite direction - turning right (left) in front of other vehicle
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up slight
Road width (m):	11.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER55

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	602	Longitudinal Traffic - veh. and follower 2nd lane
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	13.4	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	construction zone
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER56

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Not injured	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	423	Pedestrian crossing - from the right onto roadway - while passing
CADAS accident type 1:	A-8.02	A-8.02 Pedestrian crossing street - no turning of vehicle - at a junction
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	8	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Unknown	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE CER57

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	00:00-04:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.10	A-12.10 At least two vehicles - same road - opposite direction - turning right (left) in front of other vehicle
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	8	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER58

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		Yes	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	751	others - animal on roadway - deer/wild animal
CADAS accident type 1:	A-10.01	A-10.01 Single vehicle accidents with animals
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	21	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER59

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Thursday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	20:00-23:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	9	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER61

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	9	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER63

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		Yes	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	101	Driving accident- left turn
CADAS accident type 1:	A-10.06	A-10.06 Single vehicle accident - Leaving straight road - either side of the road
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER64

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Monday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	581	Resting Traffic - door getting in/out on the right
CADAS accident type 1:	A-9.03	A-9.03 Accidents with parked vehicles - opening doors
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER66

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	623	Longitudinal Traffic - veh. waiting mendatory and follower before intersection or traffic light
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	20	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER67

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Sunday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	20:00-23:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER68

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Greece		
Day of the week:	Monday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	20:00-23:59		**Alcohol involvement?**	Yes		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	151	Driving accident- gradient and left turn
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Left sharp
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER69

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Greece		
Day of the week:	Friday		**Area classification:**	Rural		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	683	Longitudinal Traffic - encountering vehicles at turning priority road
CADAS accident type 1:	A-11.06	A-11.06 At least two vehicles - head on collision in general
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Left sharp
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	8	**Bend direction at location:**	Not Applicable
Camber:	Not applicable	**Construction / maintenance zone?**	none
Road surface type:	brick	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER70

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Sunday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Industrial	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Yes	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	162	Driving accident- traffic island and right turn
CADAS accident type 1:	A-10.08	A-10.08 Single vehicle accidents on the road
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Left
Speed Limit (km/h):	40	**Vertical geometry at location:**	Down slight
Road width (m):	12	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER71

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	0	0	1	0
Max Severity	-	Slight	-	-	Not injured	-

Collision Scenario		
DaCoTA accident type:	601	Longitudinal traffic ? veh. and follower 1st lane
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	-
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	9	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER72

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	A-10.08	A-10.08 Single vehicle accidents on the road
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	7.6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	oil
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER73

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5	**Bend direction at location:**	Not Applicable
Camber:	Not applicable	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Possibly (give details and take photos)
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER74

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Wednesday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	17:00-19:59		**Alcohol involvement?**	No		
Junction type:	Y-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.16	A-12.16 At least two vehicles - different roads - turning left (right) into traffic from the right (left) side
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6.5	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Unknown	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vegetation, embankment	

SaferWheels Study - CASE CER77

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Greece	
Day of the week:	Sunday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	00:00-04:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	101	Driving accident- left turn
CADAS accident type 1:	A-10.06	A-10.06 Single vehicle accident - Leaving straight road - either side of the road
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	110	**Vertical geometry at location:**	Level
Road width (m):	20	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	Yes
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER80

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up slight
Road width (m):	8	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER81

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Saturday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	17:00-19:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6.4	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Unknown	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Parked vehicles	

SaferWheels Study - CASE CER82

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	00:00-04:59		**Alcohol involvement?**		Yes	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	421	Pedestrian crossing - from the right onto roadway
CADAS accident type 1:	A-8.01	A-8.01 Pedestrian crossing street - no turning of vehicle - outside a junction
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Parked vehicles	

SaferWheels Study - CASE CER83

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Greece		
Day of the week:	Monday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	421	Pedestrian crossing - from the right onto roadway
CADAS accident type 1:	A-8.01	A-8.01 Pedestrian crossing street - no turning of vehicle - outside a junction
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	20	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER84

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	543	Resting Traffic - stopping/parking opposite direction to the left
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	13	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER85

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		-	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	5.7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER86

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	623	Longitudinal Traffic - veh. waiting mendatory and follower before intersection or traffic light
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	17.4	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER87

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Not injured	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	401	Pedestrian crossing from left onto roadway without obstacle
CADAS accident type 1:	A-8.01	A-8.01 Pedestrian crossing street - no turning of vehicle - outside a junction
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	20	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER88

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	324	crossing - veh. with right of way from right and turning right with additional lane
CADAS accident type 1:	A-12.14	A-12.14 At least two vehicles - different roads - turning right (left) - head on collision
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	Light	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Right sharp
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10	**Bend direction at location:**	Bend right
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Unknown	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		-	
- Main cause of sight restrictions		Parked vehicles	

SaferWheels Study - CASE CER89

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Thursday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER90

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Greece		
Day of the week:	Sunday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	00:00-04:59		**Alcohol involvement?**	Yes		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	681	Longitudinal Traffic - encountering vehicles on roadway
CADAS accident type 1:	A-11.06	A-11.06 At least two vehicles - head on collision in general
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up slight
Road width (m):	10.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER91

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	6	**Bend direction at location:**	Not Applicable
Camber:	Not applicable	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Parked vehicles	

SaferWheels Study - CASE CER92

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Monday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	20:00-23:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	A-10.08	A-10.08 Single vehicle accidents on the road
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6	**Bend direction at location:**	Not Applicable
Camber:	Not applicable	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER93

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	A-10.08	A-10.08 Single vehicle accidents on the road
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	18	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	lane grooves	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER94

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Greece		
Day of the week:	Thursday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	40	**Vertical geometry at location:**	Level
Road width (m):	5.4	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	construction zone
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Unknown	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER95

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Greece	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		Yes	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	401	Pedestrian crossing from left onto roadway without obstacle
CADAS accident type 1:	A-8.01	A-8.01 Pedestrian crossing street - no turning of vehicle - outside a junction
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	14	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER96

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Greece		
Day of the week:	Saturday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Residential		
Year:	2017		**Animal involvement?**	No		
Time band:	00:00-04:59		**Alcohol involvement?**	Yes		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	A-10.06	A-10.06 Single vehicle accident - Leaving straight road - either side of the road
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CER97

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Greece		
Day of the week:	Wednesday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Residential		
Year:	2017		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	2	0	0	0
Max Severity	Fatal	-	Slight	-	-	-

Collision Scenario		
DaCoTA accident type:	601	Longitudinal traffic ? veh. and follower 1st lane
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	-	-
CADAS accident type 3:	-	-

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	90	**Vertical geometry at location:**	Level
Road width (m):	38	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL2

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Italy		
Day of the week:	Monday		**Area classification:**	Urban		
Season:	Winter		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	Unknown		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	40	**Vertical geometry at location:**	Level
Road width (m):	11.5	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Other	

SaferWheels Study - CASE CTL3

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Italy		
Day of the week:	Thursday		**Area classification:**	Urban		
Season:	Winter		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	05:00-08:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	303	crossing - veh. with right of way from left and turning right
CADAS accident type 1:	A-12.13	A-12.13 At least two vehicles - different roads - turning right (left) in front of vehicle from the left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Right sharp
Speed Limit (km/h):	40	**Vertical geometry at location:**	Level
Road width (m):	9.7	**Bend direction at location:**	Unknown
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	-	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	-	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Other	

SaferWheels Study - CASE CTL4

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Italy	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	-		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Not injured	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6.5	**Bend direction at location:**	Bend left
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL5

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Italy		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Winter		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Not injured	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	232	Turning of accident - following veh. besides right turning veh.
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	-	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL6

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Italy		
Day of the week:	Monday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	-		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	323	crossing - veh. with right of way from right and turning right
CADAS accident type 1:	A-12.14	A-12.14 At least two vehicles - different roads - turning right (left) - head on collision
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	7.18	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		walls / dwellings	

SaferWheels Study - CASE CTL7

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	232	Turning of accident - following veh. besides right turning veh.
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL8

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Italy		
Day of the week:	Monday		**Area classification:**	Rural		
Season:	Winter		**Accident environment:**	Other		
Year:	2016		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Unknown	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Other
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL9

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	-	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	A-11.08	A-11.08 At least two vehicles - opposite direction no turning - others
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	-
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.45	**Bend direction at location:**	-
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL10

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	201	Turning of accident - following veh. behind left turning veh.
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Darkness
Snowfall:	No	**Cloud cover:**	Not applicable
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.65	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL11

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Not injured	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	-
Speed Limit (km/h):	50	**Vertical geometry at location:**	-
Road width (m):	10	**Bend direction at location:**	-
Camber:	-	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Not applicable	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL12

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Not injured	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.35	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	-	**Special lane type:**	No
Road barrier present?	-	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	-	**Signage contributed to accident?**	No
Road surface defects:	-	**Road surface contaminants?**	-
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study – CASE CTL13

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Unknown	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	422	Pedestrian crossing - from the right onto roadway - while overtaking
CADAS accident type 1:	A-8.01	A-8.01 Pedestrian crossing street - no turning of vehicle - outside a junction
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	-
Speed Limit (km/h):	50	**Vertical geometry at location:**	-
Road width (m):	8.73	**Bend direction at location:**	-
Camber:	-	**Construction / maintenance zone?**	Not applicable
Road surface type:	-	**Special lane type:**	No
Road barrier present?	-	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	-	**Signage contributed to accident?**	No
Road surface defects:	-	**Road surface contaminants?**	-
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL14

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.08	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL15

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Monday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	231	Turning of accident - following veh. behind right turning veh.
CADAS accident type 1:	A-12.01	A-12.01 At least two vehicles - turning - same road - same direction - rear end collision
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up steep
Road width (m):	5.51	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	Not applicable
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL16

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	-
Speed Limit (km/h):	50	**Vertical geometry at location:**	-
Road width (m):	9.6	**Bend direction at location:**	-
Camber:	-	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		-	
- Main cause of sight restrictions		-	

SaferWheels Study - CASE CTL17

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Unknown	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	4.4	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL18

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	562	Resting Traffic - parking out forward from perpendicular position on the left
CADAS accident type 1:	A-12.19	A-12.19 At least two vehicles - crossing or turning - other
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	40	**Vertical geometry at location:**	Level
Road width (m):	5.2	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL19

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Saturday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Yes	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	601	Longitudinal traffic ? veh. and follower 1st lane
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Not applicable
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10.6	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL20

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Saturday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Yes	
Junction type:	roundabout		**Drug involvement?**		Yes	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Unknown	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	182	Driving accident- bumpy road and right turn
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.83	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL21

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Saturday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	9.6	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Not applicable
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL22

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10.69	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL23

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Italy		
Day of the week:	Thursday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	17:00-19:59		**Alcohol involvement?**	No		
Junction type:	Y-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Not injured	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Left
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL24

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	1	0	0
Max Severity	Not injured	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	711	Other accident - backing up encountering vehicle from behind
CADAS accident type 1:	A-11.07	A-11.07 At least two vehicles - opposite direction no turning - reversing
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.98	**Bend direction at location:**	Not Applicable
Camber:	Not applicable	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL25

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Unknown
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.3	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL26

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Industrial	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	21.37	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL28

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	721	Others - veh. turning around and traffic from behind
CADAS accident type 1:	A-12.02	A-12.02 At least two vehicles - turning - same road - same direction - U-turn in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	-
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.27	**Bend direction at location:**	-
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL29

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	251	Turning of accident - two veh. turning left
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.68	**Bend direction at location:**	-
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL30

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	-
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	11.31	**Bend direction at location:**	-
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL31

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	231	Turning of accident - following veh. behind right turning veh.
CADAS accident type 1:	A-12.01	A-12.01 At least two vehicles - turning - same road - same direction - rear end collision
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	11.51	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL32

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	2	0	0	0
Max Severity	Not injured	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	601	Longitudinal traffic ? veh. and follower 1st lane
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	9.21	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL33

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Industrial	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	201	Turning of accident - following veh. behind left turning veh.
CADAS accident type 1:	A-12.01	A-12.01 At least two vehicles - turning - same road - same direction - rear end collision
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6.2	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL34

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Not injured	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	11.21	**Bend direction at location:**	Not Applicable
Camber:	Not applicable	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL35

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	312	crossing - passing veh. with right of way from the left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	11.76	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL36

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Italy		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.63	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL42

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Not injured	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	312	crossing - passing veh. with right of way from the left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Left
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	9.51	**Bend direction at location:**	-
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL43

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Saturday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	322	crossing - veh. with right of way from right and turning left
CADAS accident type 1:	A-12.16	A-12.16 At least two vehicles - different roads - turning left (right) into traffic from the right (left) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	-
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8	**Bend direction at location:**	-
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL46

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	-
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.25	**Bend direction at location:**	-
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL51

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Italy		
Day of the week:	Friday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.8	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL52

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Unknown	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	581	Resting Traffic - door getting in/out on the right
CADAS accident type 1:	A-9.03	A-9.03 Accidents with parked vehicles - opening doors
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.5	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL53

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	201	Turning of accident - following veh. behind left turning veh.
CADAS accident type 1:	A-12.01	A-12.01 At least two vehicles - turning - same road - same direction - rear end collision
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	-
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8	**Bend direction at location:**	-
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL54

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	-
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	11.33	**Bend direction at location:**	-
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	-	**Special lane type:**	No
Road barrier present?	-	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	-	**Signage contributed to accident?**	No
Road surface defects:	-	**Road surface contaminants?**	-
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL58

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	12.5	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL59

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	-
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10.04	**Bend direction at location:**	-
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	Not applicable
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL60

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Not injured	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	332	crossing - passing veh. with right of way from the right and turning left
CADAS accident type 1:	A-12.16	A-12.16 At least two vehicles - different roads - turning left (right) into traffic from the right (left) side
CADAS accident type 2:	A-11.04	A-11.04 At least two vehicles - same direction - side collision
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	-
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	10.27	**Bend direction at location:**	-
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL61

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Not injured	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	9.5	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL62

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Commercial	
Year:	2017		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	232	Turning of accident - following veh. besides right turning veh.
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6.6	**Bend direction at location:**	Bend right
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Other	

SaferWheels Study - CASE CTL63

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Italy		
Day of the week:	Monday		**Area classification:**	Urban		
Season:	Winter		**Accident environment:**	Residential		
Year:	2017		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	-	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	281	Turning of accident - veh. turning left with green arrow light and oncoming traffic ahead
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.4	**Bend direction at location:**	Bend left
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Other	

SaferWheels Study - CASE CTL66

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Not injured	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	571	Resting Traffic - parking out backward from perpendicular position on the right
CADAS accident type 1:	A-11.07	A-11.07 At least two vehicles - opposite direction no turning - reversing
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	-
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.81	**Bend direction at location:**	-
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Not applicable
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL67

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	721	Others - veh. turning around and traffic from behind
CADAS accident type 1:	A-12.02	A-12.02 At least two vehicles - turning - same road - same direction - U-turn in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Not applicable	**Horizontal geometry at location:**	-
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.81	**Bend direction at location:**	-
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Not applicable
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL68

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Winter		**Accident environment:**		Commercial	
Year:	2017		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	332	crossing - passing veh. with right of way from the right and turning left
CADAS accident type 1:	A-12.16	A-12.16 At least two vehicles - different roads - turning left (right) into traffic from the right (left) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	40	**Vertical geometry at location:**	Level
Road width (m):	11	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	-	**Special lane type:**	No
Road barrier present?	-	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	-	**Signage contributed to accident?**	No
Road surface defects:	-	**Road surface contaminants?**	-
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL70

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Saturday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Not injured	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	303	crossing - veh. with right of way from left and turning right
CADAS accident type 1:	A-12.13	A-12.13 At least two vehicles - different roads - turning right (left) in front of vehicle from the left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	13.65	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL71

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	2	0	0	0	0	0
Max Severity	Unknown	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10.65	**Bend direction at location:**	Not Applicable
Camber:	Not applicable	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL72

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	312	crossing - passing veh. with right of way from the left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Not applicable	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL73

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Sunday		**Area classification:**		Rural	
Season:	Winter		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	roundabout		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Unknown	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	182	Driving accident- bumpy road and right turn
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.25	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL74

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	2	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	551	Resting Traffic - starting/parking out longitudinal on the right, same direction
CADAS accident type 1:	A-9.01	A-9.01 Hitting parked vehicles right (left) side of the road
CADAS accident type 2:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10.2	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL75

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Tuesday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Industrial	
Year:	2017		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Not injured	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	232	Turning of accident - following veh. besides right turning veh.
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5.8	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL76

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2017		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.92	**Bend direction at location:**	Bend left
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL81

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	roundabout		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10.21	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		-	

SaferWheels Study - CASE CTL82

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	1	0	0
Max Severity	Unknown	-	Not injured	Not injured	-	-

Collision Scenario		
DaCoTA accident type:	661	Longitudinal Traffic - overtaking veh. and oncoming traffic
CADAS accident type 1:	A-11.01	A-11.01 At least two vehicles - same direction - overtaking
CADAS accident type 2:	A-11.08	A-11.08 At least two vehicles - opposite direction no turning - others
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	9.72	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Not applicable
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL83

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Tuesday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	6.6	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Not applicable
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL84

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Italy		
Day of the week:	Wednesday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Residential		
Year:	2017		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Not applicable	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.9	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	-	**Special lane type:**	No
Road barrier present?	-	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	-	**Signage contributed to accident?**	No
Road surface defects:	-	**Road surface contaminants?**	-
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL85

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	2	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	631	Longitudinal Traffic - lane change to the left because of veh. ahead and follower
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	A-11.04	A-11.04 At least two vehicles - same direction - side collision
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	9.11	**Bend direction at location:**	Bend left
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL86

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Wednesday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Industrial	
Year:	2017		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Unknown	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	732	others - moving obstacle - others
CADAS accident type 1:	A-10.02	A-10.02 Single vehicle accidents with obstacles on or above the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.58	**Bend direction at location:**	Bend left
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL87

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Saturday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Unknown	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.10	A-12.10 At least two vehicles - same road - opposite direction - turning right (left) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	9	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL88

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	204	Turning of accident - veh. that changes lane for turning left and following veh.
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.78	**Bend direction at location:**	Bend right
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Not applicable	
- Main cause of sight restrictions		Other	

SaferWheels Study - CASE CTL89

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Wednesday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL90

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	16.11	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL91

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Monday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Unknown	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL92

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Fatal	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Right light
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	5.25	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL93

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	-	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	11.6	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL95

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Not injured	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	611	Longitudinal Traffic - congestion and follower 1st lane
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.2	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL96

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Italy		
Day of the week:	Thursday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Residential		
Year:	2017		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	6.2	**Bend direction at location:**	Bend right
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	-	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Other	

SaferWheels Study - CASE CTL98

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Italy	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Unknown	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	623	Longitudinal Traffic - veh. waiting mendatory and follower before intersection or traffic light
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10.5	**Bend direction at location:**	Bend right
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL99

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	2	0	0	0
Max Severity	-	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	581	Resting Traffic - door getting in/out on the right
CADAS accident type 1:	A-9.03	A-9.03 Accidents with parked vehicles - opening doors
CADAS accident type 2:	A-11.04	A-11.04 At least two vehicles - same direction - side collision
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Not applicable
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE CTL101

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Italy	
Day of the week:	Saturday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2017		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	-	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6.3	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	-	**Special lane type:**	No
Road barrier present?	-	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	-	**Signage contributed to accident?**	No
Road surface defects:	-	**Road surface contaminants?**	-
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS1

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Poland	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	721	Others - veh. turning around and traffic from behind
CADAS accident type 1:	A-12.02	A-12.02 At least two vehicles - turning - same road - same direction - U-turn in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	20-25 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE ITS2

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Sunday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	721	Others - veh. turning around and traffic from behind
CADAS accident type 1:	A-12.02	A-12.02 At least two vehicles - turning - same road - same direction - U-turn in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	20-25 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.2	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE ITS3

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Friday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	slip road/ ramp		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	635	Longitudinal Traffic - lane change to the left after passing on the right and follower
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	20-25 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Left
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up
Road width (m):	7.2	**Bend direction at location:**	Bend left
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS4

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Poland	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	1	0
Max Severity	Slight	-	-	-	Not injured	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	12	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS5

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Poland	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	303	crossing - veh. with right of way from left and turning right
CADAS accident type 1:	A-12.13	A-12.13 At least two vehicles - different roads - turning right (left) in front of vehicle from the left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS6

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Saturday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	Y-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	0	0	0	1
Max Severity	-	Slight	-	-	-	Not injured

Collision Scenario		
DaCoTA accident type:	371	crossing - crossing bicycle from the right side
CADAS accident type 1:	A-12.08	A-12.08 At least two vehicles - same road - opposite direction - turning into same road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	4.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	Not applicable
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS7

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Saturday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	20:00-23:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Darkness
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	100	**Vertical geometry at location:**	Level
Road width (m):	7.2	**Bend direction at location:**	Not Applicable
Camber:	Not applicable	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE ITS8

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Wednesday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	244	Turning of accident - right turning veh. and cyclist from bicycle lane in opposite direction
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6	**Bend direction at location:**	Bend right
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		atmospheric conditions	

SaferWheels Study - CASE ITS9

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Thursday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.14	A-12.14 At least two vehicles - different roads - turning right (left) - head on collision
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Parked vehicles	

SaferWheels Study - CASE ITS10

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Sunday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	17:00-19:59		**Alcohol involvement?**	No		
Junction type:	roundabout		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	12	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS11

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	20:00-23:59		**Alcohol involvement?**	Yes		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Fatal	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	379	crossing - unknown if 371-374
CADAS accident type 1:	-	-
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Not applicable
Road width (m):	13.1	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS12

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Poland	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	281	Turning of accident - veh. turning left with green arrow light and oncoming traffic ahead
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	14	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		atmospheric conditions	

SaferWheels Study - CASE ITS13

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Friday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	281	Turning of accident - veh. turning left with green arrow light and oncoming traffic ahead
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	60	**Vertical geometry at location:**	Level
Road width (m):	11	**Bend direction at location:**	Bend right
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Possibly (comment)
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS14

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	722	others - veh. turning around and oncoming traffic
CADAS accident type 1:	A-12.07	A-12.07 At least two vehicles - same road - opposite direction - U-turn in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	9.4	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	Not applicable
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS15

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Poland	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	Not applicable
Road surface type:	0	**Special lane type:**	No
Road barrier present?	0	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	0	**Signage contributed to accident?**	No
Road surface defects:	0	**Road surface contaminants?**	0
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE ITS16

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Poland	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Not injured	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	421	Pedestrian crossing - from the right onto roadway
CADAS accident type 1:	A-8.01	A-8.01 Pedestrian crossing street - no turning of vehicle - outside a junction
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	14	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vegetation, embankment	

SaferWheels Study - CASE ITS17

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Poland	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.10	A-12.10 At least two vehicles - same road - opposite direction - turning right (left) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	20-25 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS18

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Sunday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	17:00-19:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	542	Resting Traffic - stopping/parking same direction to the left
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.4	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS19

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	9.8	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE ITS20

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Poland	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	1	0	0
Max Severity	Slight	-	-	Not injured	-	-

Collision Scenario		
DaCoTA accident type:	635	Longitudinal Traffic - lane change to the left after passing on the right and follower
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	-
Snowfall:	No	**Cloud cover:**	-
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	17	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS21

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Monday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	371	crossing - crossing bicycle from the right side
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Parked vehicles	

SaferWheels Study - CASE ITS22

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Thursday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	multiple, comment
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Parked vehicles	

SaferWheels Study - CASE ITS23

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	561	Resting Traffic - parking out forward from perpendicular position on the right
CADAS accident type 1:	A-11.07	A-11.07 At least two vehicles - opposite direction no turning - reversing
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS24

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Poland	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.14	A-12.14 At least two vehicles - different roads - turning right (left) - head on collision
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	9	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS25

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	543	Resting Traffic - stopping/parking opposite direction to the left
CADAS accident type 1:	A-12.07	A-12.07 At least two vehicles - same road - opposite direction - U-turn in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Darkness
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.2	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS26

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Friday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	17:00-19:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	542	Resting Traffic - stopping/parking same direction to the left
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS27

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	0	1	0	0
Max Severity	-	Fatal	-	Not injured	-	-

Collision Scenario		
DaCoTA accident type:	651	Longitudinal Traffic - parallel driving in same direction
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	60	**Vertical geometry at location:**	Level
Road width (m):	11	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE ITS28

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Fatal	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	Light	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Other	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS29

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Thursday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	05:00-08:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		walls / dwellings	

SaferWheels Study - CASE ITS30

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Saturday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.14	A-12.14 At least two vehicles - different roads - turning right (left) - head on collision
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		walls / dwellings	

SaferWheels Study - CASE ITS31

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Poland	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	1	0
Max Severity	Slight	-	Not injured	-	Not injured	-

Collision Scenario		
DaCoTA accident type:	631	Longitudinal Traffic - lane change to the left because of veh. ahead and follower
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10.2	**Bend direction at location:**	Not Applicable
Camber:	Not applicable	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS32

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Wednesday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	17:00-19:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	303	crossing - veh. with right of way from left and turning right
CADAS accident type 1:	A-12.13	A-12.13 At least two vehicles - different roads - turning right (left) in front of vehicle from the left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	20-25 m/s

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	9	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS33

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Monday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	342	crossing - bicycle with right of way from bicycle lane right and straight
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	20-25 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Left
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS34

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Poland	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	2	1	0	0	0	0
Max Severity	Not injured	Slight	-	-	-	-

Collision Scenario		
DaCoTA accident type:	652	Longitudinal Traffic - parallel driving during overtaking - in same direction
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6	**Bend direction at location:**	Not Applicable
Camber:	Not applicable	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Not applicable
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS35

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Poland	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	341	crossing - bicycle with right of way from bicycle lane left and straight
CADAS accident type 1:	A-12.10	A-12.10 At least two vehicles - same road - opposite direction - turning right (left) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		urban furniture	

SaferWheels Study - CASE ITS36

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Sunday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	661	Longitudinal Traffic - overtaking veh. and oncoming traffic
CADAS accident type 1:	A-11.08	A-11.08 At least two vehicles - opposite direction no turning - others
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	20-25 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE ITS37

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Yes	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	543	Resting Traffic - stopping/parking opposite direction to the left
CADAS accident type 1:	AA-12.52	AA-12.52 At least two vehicles - turning or crossing - same road - opposite direction - not specified
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6.2	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS38

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	561	Resting Traffic - parking out forward from perpendicular position on the right
CADAS accident type 1:	AA-11.52	AA-11.52 At least two vehicles - opposite direction no turning - not specified
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS39

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		urban furniture	

SaferWheels Study - CASE ITS40

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	646	Longitudinal Traffic - lane change to the right after passing on parallel lane and follower
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study – CASE ITS41

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Poland	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	244	Turning of accident - right turning veh. and cyclist from bicycle lane in opposite direction
CADAS accident type 1:	A-12.10	A-12.10 At least two vehicles - same road - opposite direction - turning right (left) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10.2	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS42

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Saturday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	303	crossing - veh. with right of way from left and turning right
CADAS accident type 1:	A-12.13	A-12.13 At least two vehicles - different roads - turning right (left) in front of vehicle from the left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		signs	

SaferWheels Study – CASE ITS43

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Sunday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	303	crossing - veh. with right of way from left and turning right
CADAS accident type 1:	A-12.16	A-12.16 At least two vehicles - different roads - turning left (right) into traffic from the right (left) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	9	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS44

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Wednesday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	224	Turning of accident - left turning veh. and cyclist from bicycle lane in opposite direction
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down
Road width (m):	6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS45

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Poland	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	562	Resting Traffic - parking out forward from perpendicular position on the left
CADAS accident type 1:	-	-
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Parked vehicles	

SaferWheels Study - CASE ITS46

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Poland	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		Not Applicable	
Time band:	13:00-16:59		**Alcohol involvement?**		Not Applicable	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	244	Turning of accident - right turning veh. and cyclist from bicycle lane in opposite direction
CADAS accident type 1:	AA-12.51	AA-12.51 At least two vehicles - turning - same road - same direction - not specified
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	25+ m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.8	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS47

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Poland	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	371	crossing - crossing bicycle from the right side
CADAS accident type 1:	A-8.02	A-8.02 Pedestrian crossing street - no turning of vehicle - at a junction
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Left
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6.2	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS48

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	561	Resting Traffic - parking out forward from perpendicular position on the right
CADAS accident type 1:	A-12.99	A-12.99 At least two vehicles - crossing or turning - unknown
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	25+ m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Parked vehicles	

SaferWheels Study – CASE ITS49

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	371	crossing - crossing bicycle from the right side
CADAS accident type 1:	A-12.14	A-12.14 At least two vehicles - different roads - turning right (left) - head on collision
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	20-25 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	block	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Not applicable
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Parked vehicles	

SaferWheels Study - CASE ITS50

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	Poland		
Day of the week:	Wednesday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	661	Longitudinal Traffic - overtaking veh. and oncoming traffic
CADAS accident type 1:	A-11.99	A-11.99 At least two vehicles - no turning - unknown
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS51

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Friday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Commercial		
Year:	2015		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	Yes		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	281	Turning of accident - veh. turning left with green arrow light and oncoming traffic ahead
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	20-25 m/s

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE ITS52

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Poland	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		Yes	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	285	Turning of accident - veh. turning right with green arrow light and bicycle on bicycle lane
CADAS accident type 1:	A-12.99	A-12.99 At least two vehicles - crossing or turning - unknown
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	12	**Bend direction at location:**	Not Applicable
Camber:	Negative	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Possibly (comment)
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Other	

SaferWheels Study - CASE ITS53

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Residential		
Year:	2016		**Animal involvement?**	No		
Time band:	00:00-04:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	371	crossing - crossing bicycle from the right side
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.8	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vegetation, embankment	

SaferWheels Study - CASE ITS54

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	05:00-08:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Left
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Multiple, comment	**Road surface contaminants?**	mud
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		walls / dwellings	

SaferWheels Study - CASE ITS55

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Poland	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	799	others - all other accidents
CADAS accident type 1:	AA-11.51	AA-11.51 At least two vehicles - same direction no turning - not specified
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Other	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	20-25 m/s

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up slight
Road width (m):	9	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS56

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Friday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	3.5	**Bend direction at location:**	Bend right
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS57

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	0	1	0	0
Max Severity	-	Fatal	-	Not injured	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Damp	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS58

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	05:00-08:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	244	Turning of accident - right turning veh. and cyclist from bicycle lane in opposite direction
CADAS accident type 1:	-	-
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS59

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	534	Resting Traffic - evading veh. and pedestrian in same direction and parking veh. on the left
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	Not applicable
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS60

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.9	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS61

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Sunday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		Yes	
Junction type:	No junction		**Drug involvement?**		Yes	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	A-10.05	A-10.05 Single vehicle accidents with obstacles - others
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	90	**Vertical geometry at location:**	Down slight
Road width (m):	5.2	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	Ye
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS62

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	Poland		
Day of the week:	Friday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Commercial		
Year:	2016		**Animal involvement?**	No		
Time band:	05:00-08:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	581	Resting Traffic - door getting in/out on the right
CADAS accident type 1:	A-9.03	A-9.03 Accidents with parked vehicles - opening doors
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	9	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS63

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Saturday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	00:00-04:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	AA-12.52	AA-12.52 At least two vehicles - turning or crossing - same road - opposite direction - not specified
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	60	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS64

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Tuesday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	102	Driving accident- right turn
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Darkness
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	70	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Bend right
Camber:	Negative	**Construction / maintenance zone?**	none
Road surface type:	0	**Special lane type:**	Yes
Road barrier present?	0	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	0	**Signage contributed to accident?**	No
Road surface defects:	0	**Road surface contaminants?**	0
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS65

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Yes	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Fatal	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	553	Resting Traffic - starting/parking out longitudinal on the right, opposite direction
CADAS accident type 1:	A-12.05	A-12.05 At least two vehicles - turning - same road - same direction - others
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Darkness
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS66

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		Yes	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	635	Longitudinal Traffic - lane change to the left after passing on the right and follower
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	90	**Vertical geometry at location:**	Level
Road width (m):	5.7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS67

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Tuesday		**Area classification:**		Rural	
Season:	Winter		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		Yes	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	90	**Vertical geometry at location:**	Level
Road width (m):	4.8	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS68

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	0	1	0	0
Max Severity	-	Fatal	-	Not injured	-	-

Collision Scenario		
DaCoTA accident type:	344	crossing - bicycle with right of way from oncoming bicycle lane right and straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS69

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	0	0	1	0
Max Severity	-	Fatal	-	-	Not injured	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		walls / dwellings	

SaferWheels Study - CASE ITS70

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	682	Longitudinal Traffic - encountering vehicles in curve
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	4.5	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS71

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	561	Resting Traffic - parking out forward from perpendicular position on the right
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	block	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		walls / dwellings	

SaferWheels Study - CASE ITS72

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Fatal	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	371	crossing - crossing bicycle from the right side
CADAS accident type 1:	A-8.01	A-8.01 Pedestrian crossing street - no turning of vehicle - outside a junction
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10.3	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS73

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6.2	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS74

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	285	Turning of accident - veh. turning right with green arrow light and bicycle on bicycle lane
CADAS accident type 1:	A-8.03	A-8.03 Pedestrians crossing - turning of vehicle - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	15	**Bend direction at location:**	Not Applicable
Camber:	-	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS75

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Sunday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	201	Turning of accident - following veh. behind left turning veh.
CADAS accident type 1:	A-12.01	A-12.01 At least two vehicles - turning - same road - same direction - rear end collision
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5.9	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS76

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Saturday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		Yes	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	553	Resting Traffic - starting/parking out longitudinal on the right, opposite direction
CADAS accident type 1:	A-11.06	A-11.06 At least two vehicles - head on collision in general
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Darkness
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	90	**Vertical geometry at location:**	Level
Road width (m):	5	**Bend direction at location:**	Not Applicable
Camber:	Not applicable	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE ITS77

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS78

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	471	Pedestrian crossing - from the right behind intersection
CADAS accident type 1:	A-8.01	A-8.01 Pedestrian crossing street - no turning of vehicle - outside a junction
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Darkness
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	100	**Vertical geometry at location:**	Level
Road width (m):	7.7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Possibly (comment)
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		temporary signs	

SaferWheels Study - CASE ITS79

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	652	Longitudinal Traffic - parallel driving during overtaking - in same direction
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Left
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS80

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	721	Others - veh. turning around and traffic from behind
CADAS accident type 1:	A-12.02	A-12.02 At least two vehicles - turning - same road - same direction - U-turn in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6	**Bend direction at location:**	Bend right
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS81

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS82

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Sunday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	101	Driving accident- left turn
CADAS accident type 1:	A-10.06	A-10.06 Single vehicle accident - Leaving straight road - either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	20-25 m/s

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	90	**Vertical geometry at location:**	Level
Road width (m):	5.1	**Bend direction at location:**	Not Applicable
Camber:	Not applicable	**Construction / maintenance zone?**	none
Road surface type:	0	**Special lane type:**	No
Road barrier present?	0	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	0	**Signage contributed to accident?**	No
Road surface defects:	0	**Road surface contaminants?**	0
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS83

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.16	A-12.16 At least two vehicles - different roads - turning left (right) into traffic from the right (left) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6.6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS84

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Wednesday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	661	Longitudinal Traffic - overtaking veh. and oncoming traffic
CADAS accident type 1:	A-10.06	A-10.06 Single vehicle accident - Leaving straight road - either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	90	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	0	**Special lane type:**	No
Road barrier present?	0	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	0	**Signage contributed to accident?**	No
Road surface defects:	0	**Road surface contaminants?**	0
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS85

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	543	Resting Traffic - stopping/parking opposite direction to the left
CADAS accident type 1:	A-12.10	A-12.10 At least two vehicles - same road - opposite direction - turning right (left) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS86

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		Poland	
Day of the week:	Sunday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	90	**Vertical geometry at location:**	Level
Road width (m):	7.2	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	Not applicable
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE ITS87

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		Poland	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	244	Turning of accident - right turning veh. and cyclist from bicycle lane in opposite direction
CADAS accident type 1:	-	-
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	12	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE SWO1

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Commercial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	2	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	611	Longitudinal Traffic - congestion and follower 1st lane
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	80	**Vertical geometry at location:**	Down slight
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO2

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Commercial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	1
Max Severity	Fatal	-	-	-	-	Not injured

Collision Scenario		
DaCoTA accident type:	361	crossing - unguarded railway crossing on intersection
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	tram rails	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO3

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Saturday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		Unknown	
Junction type:	roundabout		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.19	A-12.19 At least two vehicles - crossing or turning - other
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Not applicable	**Bend direction at location:**	Not Applicable
Camber:	Not applicable	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO4

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Industrial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	322	crossing - veh. with right of way from right and turning left
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	60	**Vertical geometry at location:**	Level
Road width (m):	14.15	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Possibly (comment)
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO5

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Other	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Other	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	1	0	0	0	0
Max Severity	Serious	Slight	-	-	-	-

Collision Scenario		
DaCoTA accident type:	661	Longitudinal Traffic - overtaking veh. and oncoming traffic
CADAS accident type 1:	A-11.08	A-11.08 At least two vehicles - opposite direction no turning - others
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light (indoor)
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Not applicable	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	Not applicable	**Vertical geometry at location:**	Level
Road width (m):	4.73	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	Unknown	**Special lane type:**	Yes
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	potholes	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO6

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Not injured	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	342	crossing - bicycle with right of way from bicycle lane right and straight
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Other
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO7

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Unknown	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	2	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	9.78	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE SWO8

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		Unknown	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	223	Turning of accident - left turning veh. and cyclist from bicycle lane in same direction
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	6.3	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO9

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	-	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	131	Driving accident- non-straight street, bending to the left
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	60	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Bend right
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO10

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	101	Driving accident- left turn
CADAS accident type 1:	A-11.01	A-11.01 At least two vehicles - same direction - overtaking
CADAS accident type 2:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Left sharp
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6.18	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	Other
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO11

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Industrial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		Unknown	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	2	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Right light
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	7.06	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	Other	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Multiple, comment	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO12

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	215	Turning of accident - left turning veh. and oncoming, left turning vehicle
CADAS accident type 1:	A-12.09	A-12.09 At least two vehicles - same road - opposite direction - turning into opposite roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Other	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	7.26	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	brick	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Other	**Signage contributed to accident?**	No
Road surface defects:	potholes	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO13

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	1	0	0	0	0
Max Severity	Serious	Serious	-	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	4.82	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO14

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	-	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	721	Others - veh. turning around and traffic from behind
CADAS accident type 1:	A-12.02	A-12.02 At least two vehicles - turning - same road - same direction - U-turn in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5.96	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO15

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		Unknown	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	681	Longitudinal Traffic - encountering vehicles on roadway
CADAS accident type 1:	A-12.15	A-12.15 At least two vehicles - different roads - both vehicles turning
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	construction zone
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO16

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Saturday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	Unknown		**Animal involvement?**		Other	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	2.44	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	brick	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE SWO17

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	6.66	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	brick	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vegetation, embankment	

SaferWheels Study - CASE SWO18

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Sunday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Industrial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		Unknown	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	299	Turning of accident - others
CADAS accident type 1:	A-12.10	A-12.10 At least two vehicles - same road - opposite direction - turning right (left) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Left
Speed Limit (km/h):	60	**Vertical geometry at location:**	Level
Road width (m):	9.58	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Other	

SaferWheels Study - CASE SWO19

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	roundabout		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	122	Driving accident- while turning off/into another street to the right
CADAS accident type 1:	A-10.10	A-10.10 Single vehicle accidents in junctions or entrances
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up
Road width (m):	9.11	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	block	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO20

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	2	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	371	crossing - crossing bicycle from the right side
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	9.68	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO21

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	799	others - all other accidents
CADAS accident type 1:	-	-
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Right light
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	23.37	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	construction zone
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Yes (comment)
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO22

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Thursday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Industrial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	223	Turning of accident - left turning veh. and cyclist from bicycle lane in same direction
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Other
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5.46	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO23

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	271	Turning of accident - veh. from right turning priority road and other vehicle
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Other
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Left sharp
Speed Limit (km/h):	walking speed	**Vertical geometry at location:**	Level
Road width (m):	3.4	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	brick	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	lane grooves	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Parked vehicles	

SaferWheels Study - CASE SWO24

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Tuesday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Industrial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	799	others - all other accidents
CADAS accident type 1:	A-10.02	A-10.02 Single vehicle accidents with obstacles on or above the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	100	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO25

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Monday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	0	0	0	0
Max Severity	-	Serious	-	-	-	-

Collision Scenario		
DaCoTA accident type:	799	others - all other accidents
CADAS accident type 1:	A-10.02	A-10.02 Single vehicle accidents with obstacles on or above the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.82	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	brick	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Unknown	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	leaves
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO26

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	682	Longitudinal Traffic - encountering vehicles in curve
CADAS accident type 1:	A-11.06	A-11.06 At least two vehicles - head on collision in general
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	5.08	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	Other
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Damp	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		-	
- Main cause of sight restrictions		-	

SaferWheels Study - CASE SWO27

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Commercial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		Unknown	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	2	0	0	0	0
Max Severity	-	Serious	-	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO28

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	999	Unknown
CADAS accident type 1:	-	-
CADAS accident type 2:	Unknown	Unknown
CADAS accident type 3:	Unknown	Unknown

Environmental Conditions			
Rainfall:	Heavy	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	20-25 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	20.69	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	Other
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO29

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Wednesday		**Area classification:**		Rural	
Season:	Winter		**Accident environment:**		Other	
Year:	Unknown		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		Unknown	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	1	0	0	0	0
Max Severity	Not injured	Serious	-	-	-	-

Collision Scenario		
DaCoTA accident type:	342	crossing - bicycle with right of way from bicycle lane right and straight
CADAS accident type 1:	A-12.16	A-12.16 At least two vehicles - different roads - turning left (right) into traffic from the right (left) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Darkness
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	80	**Vertical geometry at location:**	Up slight
Road width (m):	4.63	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	maintenance zone
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO30

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Heavy	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	20-25 m/s

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	5.78	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	Unknown
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO31

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Industrial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		Other	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	342	crossing - bicycle with right of way from bicycle lane right and straight
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	17.94	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	construction zone
Road surface type:	block	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Parked vehicles	

SaferWheels Study - CASE SWO32

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Industrial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	341	crossing - bicycle with right of way from bicycle lane left and straight
CADAS accident type 1:	A-12.13	A-12.13 At least two vehicles - different roads - turning right (left) in front of vehicle from the left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Heavy	**Light Condition:**	Other
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	20-25 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Right light
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	7.06	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	Other	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	Multiple, comment	**Road surface contaminants?**	leaves
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO33

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	0	0	0	0
Max Severity	-	Serious	-	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	3.92	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	brick	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Unknown	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	Unknown
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		walls / dwellings	

SaferWheels Study - CASE SWO34

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	281	Turning of accident - veh. turning left with green arrow light and oncoming traffic ahead
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.26	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	brick	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO35

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	454	Pedestrian crossing - from the right before intersection - behind solid obstacle
CADAS accident type 1:	A-8.02	A-8.02 Pedestrian crossing street - no turning of vehicle - at a junction
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	20-25 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Not applicable	**Construction / maintenance zone?**	none
Road surface type:	block	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Other	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Other	

SaferWheels Study - CASE SWO36

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Commercial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	1	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up
Road width (m):	11	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	brick	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO37

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	1	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	322	crossing - veh. with right of way from right and turning left
CADAS accident type 1:	A-12.16	A-12.16 At least two vehicles - different roads - turning left (right) into traffic from the right (left) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	4.8	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Other	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		billboard	

SaferWheels Study – CASE SWO38

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Saturday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-10.02	A-10.02 Single vehicle accidents with obstacles on or above the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Other	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	Not applicable	**Vertical geometry at location:**	Level
Road width (m):	3.38	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		atmospheric conditions	

SaferWheels Study - CASE SWO39

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	244	Turning of accident - right turning veh. and cyclist from bicycle lane in opposite direction
CADAS accident type 1:	A-12.10	A-12.10 At least two vehicles - same road - opposite direction - turning right (left) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	4.6	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	brick	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO40

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Industrial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	344	crossing - bicycle with right of way from oncoming bicycle lane right and straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	60	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO41

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	0	0	1	0
Max Severity	-	Serious	-	-	Not injured	-

Collision Scenario		
DaCoTA accident type:	101	Driving accident- left turn
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5.14	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		walls / dwellings	

SaferWheels Study - CASE SWO42

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		Unknown	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	281	Turning of accident - veh. turning left with green arrow light and oncoming traffic ahead
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	Other	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO43

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	00:00-04:59		**Alcohol involvement?**		Yes	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	-	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	101	Driving accident- left turn
CADAS accident type 1:	A-10.06	A-10.06 Single vehicle accident - Leaving straight road - either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Unknown	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	Unknown
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO44

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Industrial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	2	0	0	0	0
Max Severity	-	Serious	-	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	A-10.08	A-10.08 Single vehicle accidents on the road
CADAS accident type 2:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	60	**Vertical geometry at location:**	Level
Road width (m):	5.54	**Bend direction at location:**	Not Applicable
Camber:	Positive	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Multiple, comment	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO45

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Saturday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	322	crossing - veh. with right of way from right and turning left
CADAS accident type 1:	A-12.16	A-12.16 At least two vehicles - different roads - turning left (right) into traffic from the right (left) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Other	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE SWO46

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		Other	
Time band:	05:00-08:59		**Alcohol involvement?**		Yes	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	639	Longitudinal Traffic - lane change to the left (unknown reason) and follower
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5.5	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO47

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	421	Pedestrian crossing - from the right onto roadway
CADAS accident type 1:	A-8.01	A-8.01 Pedestrian crossing street - no turning of vehicle - outside a junction
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO48

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	611	Longitudinal Traffic - congestion and follower 1st lane
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	4.2	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE SWO49

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	The Netherlands		
Day of the week:	Monday		**Area classification:**	Urban		
Season:	Spring		**Accident environment:**	Residential		
Year:	Unknown		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	Unknown		
Junction type:	crossroads		**Drug involvement?**	Unknown		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	5.66	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	-	**Special lane type:**	No
Road barrier present?	-	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	-	**Signage contributed to accident?**	No
Road surface defects:	-	**Road surface contaminants?**	-
Sight restrictions contributed to accident?		Other	
- Main cause of sight restrictions		vegetation, embankment	

SaferWheels Study - CASE SWO50

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		Yes	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	283	Turning of accident - veh. turning left with green arrow light and bicycle on bicycle lane
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	11.64	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Other	
- Main cause of sight restrictions		Other	

SaferWheels Study - CASE SWO51

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	1	0	0	0	0
Max Severity	Not injured	Serious	-	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	-	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.95	**Bend direction at location:**	Not Applicable
Camber:	-	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO52

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	Other	**Vertical geometry at location:**	Level
Road width (m):	3.9	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO53

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE SWO54

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	-		**Accident environment:**		Industrial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	102	Driving accident- right turn
CADAS accident type 1:	A-10.09	A-10.09 Single vehicle accidents including rollover
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	Other	**Vertical geometry at location:**	Level
Road width (m):	3	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	Other
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	Other
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO55

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	1	0	0	0	0
Max Severity	-	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	999	Unknown
CADAS accident type 1:	A-11.99	A-11.99 At least two vehicles - no turning - unknown
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Other	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	Not applicable	**Vertical geometry at location:**	Down slight
Road width (m):	4	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO56

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	342	crossing - bicycle with right of way from bicycle lane right and straight
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	8.1	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO57

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	672	Longitudinal Traffic - pedestrian and veh. in opposite direction - right lane
CADAS accident type 1:	A-8.08	A-8.08 Pedestrian accident - other
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Right light
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	9.93	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO58

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	243	Turning of accident - right turning veh. and cyclist from bicycle lane in same direction
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Other	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vegetation, embankment	

SaferWheels Study - CASE SWO59

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	199	Driving accident- other driving accidents
CADAS accident type 1:	A-10.06	A-10.06 Single vehicle accident - Leaving straight road - either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Other	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO60

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	1	0	0	0	0
Max Severity	Slight	Serious	-	-	-	-

Collision Scenario		
DaCoTA accident type:	699	Longitudinal Traffic - others
CADAS accident type 1:	A-11.01	A-11.01 At least two vehicles - same direction - overtaking
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Multiple, comment	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO61

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	342	crossing - bicycle with right of way from bicycle lane right and straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO62

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	-		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	1	0	0	0	0
Max Severity	Serious	Slight	-	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	Not applicable	**Vertical geometry at location:**	Level
Road width (m):	3.36	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO63

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	The Netherlands		
Day of the week:	Tuesday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Residential		
Year:	Unknown		**Animal involvement?**	No		
Time band:	09:00-12:59		**Alcohol involvement?**	No		
Junction type:	T-junction		**Drug involvement?**	Unknown		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	1	0	0	0	0
Max Severity	Serious	Not injured	-	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10.32	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	brick	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Other	

SaferWheels Study - CASE SWO64

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Saturday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	3.3	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	brick	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Parked vehicles	

SaferWheels Study - CASE SWO65

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	Unknown		**Animal involvement?**		Unknown	
Time band:	-		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	-	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	A-10.06	A-10.06 Single vehicle accident - Leaving straight road - either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Darkness
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	Not applicable	**Vertical geometry at location:**	Level
Road width (m):	5.8	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	Other	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO66

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	Other	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	brick	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO67

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	A-10.99	A-10.99 Single vehicle accidents - unknown
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	construction zone
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO68

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	Other	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE SWO69

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	roundabout		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	1	0	0	0	0
Max Severity	Not injured	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	303	crossing - veh. with right of way from left and turning right
CADAS accident type 1:	A-12.99	A-12.99 At least two vehicles - crossing or turning - unknown
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Left
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO70

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Industrial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	342	crossing - bicycle with right of way from bicycle lane right and straight
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.08	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	block	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO71

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		Unknown	
Junction type:	roundabout		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	244	Turning of accident - right turning veh. and cyclist from bicycle lane in opposite direction
CADAS accident type 1:	A-12.19	A-12.19 At least two vehicles - crossing or turning - other
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Left
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5.88	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO72

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	1	0	0	0	0
Max Severity	Serious	Serious	-	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	Other	**Vertical geometry at location:**	Level
Road width (m):	4.44	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Other	

SaferWheels Study - CASE SWO73

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Industrial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		Unknown	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	A-10.09	A-10.09 Single vehicle accidents including rollover
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO74

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		Unknown	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	271	Turning of accident - veh. from right turning priority road and other vehicle
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	8.3	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	Other	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO75

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Commercial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO76

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	581	Resting Traffic - door getting in/out on the right
CADAS accident type 1:	A-9.03	A-9.03 Accidents with parked vehicles - opening doors
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	construction zone
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Not applicable	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO77

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		Unknown	
Junction type:	roundabout		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	341	crossing - bicycle with right of way from bicycle lane left and straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	tram rails	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO78

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Saturday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	661	Longitudinal Traffic - overtaking veh. and oncoming traffic
CADAS accident type 1:	A-11.06	A-11.06 At least two vehicles - head on collision in general
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	60	**Vertical geometry at location:**	Level
Road width (m):	5.14	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Unknown
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO79

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		Unknown	
Junction type:	roundabout		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	341	crossing - bicycle with right of way from bicycle lane left and straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Left
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5.46	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	Other	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Damp	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	leaves
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO80

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Saturday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	321	crossing - veh. with right of way from right and driving straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	A-10.09	A-10.09 Single vehicle accidents including rollover
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Other
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	3.21	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	brick	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	Unknown
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		walls / dwellings	

SaferWheels Study - CASE SWO81

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Industrial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	342	crossing - bicycle with right of way from bicycle lane right and straight
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	Light	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	15-20 m/s

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	80	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	Other
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO82

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	The Netherlands		
Day of the week:	Monday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Residential		
Year:	Unknown		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	Unknown		
Junction type:	No junction		**Drug involvement?**	Unknown		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	581	Resting Traffic - door getting in/out on the right
CADAS accident type 1:	A-9.03	A-9.03 Accidents with parked vehicles - opening doors
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Left
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.5	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	leaves
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Other	

SaferWheels Study - CASE SWO83

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Industrial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	-	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	A-10.09	A-10.09 Single vehicle accidents including rollover
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	5.84	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO84

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Saturday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Yes	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	0	0	0	0
Max Severity	-	Serious	-	-	-	-

Collision Scenario		
DaCoTA accident type:	999	Unknown
CADAS accident type 1:	-	-
CADAS accident type 2:	Unknown	Unknown
CADAS accident type 3:	Unknown	Unknown

Environmental Conditions			
Rainfall:	-	**Light Condition:**	-
Snowfall:	-	**Cloud cover:**	-
Fog/Mist:	-	**Strong wind:**	-

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	4.64	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	brick	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Unknown	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	Unknown
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO85

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**	The Netherlands		
Day of the week:	Wednesday		**Area classification:**	Urban		
Season:	Autumn		**Accident environment:**	Commercial		
Year:	Unknown		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	Unknown		
Junction type:	crossroads		**Drug involvement?**	Unknown		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	0	1	0	0
Max Severity	-	Serious	-	Not injured	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	5.24	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	brick	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Damp	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	Other
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO86

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	Unknown		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		Unknown	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	326	crossing - veh. with right of way from right and turning left
CADAS accident type 1:	A-12.18	A-12.18 At least two vehicles - different roads - turning into traffic - others
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	5.98	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	brick	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Unknown	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE SWO87

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		The Netherlands	
Day of the week:	Monday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Industrial	
Year:	Unknown		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	661	Longitudinal Traffic - overtaking veh. and oncoming traffic
CADAS accident type 1:	A-11.08	A-11.08 At least two vehicles - opposite direction no turning - others
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	Light	**Strong wind:**	10-15m/s

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Right light
Speed Limit (km/h):	60	**Vertical geometry at location:**	Level
Road width (m):	5.6	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	-	**Special lane type:**	No
Road barrier present?	-	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	-	**Signage contributed to accident?**	No
Road surface defects:	Unknown	**Road surface contaminants?**	-
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR5

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	132	Driving accident- non-straight street, bending to the right
CADAS accident type 1:	A-10.08	A-10.08 Single vehicle accidents on the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	6.24	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Not applicable	**Road surface contaminants?**	oil
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR7

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Monday		**Area classification:**		Rural	
Season:	Winter		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	652	Longitudinal Traffic - parallel driving during overtaking - in same direction
CADAS accident type 1:	A-11.01	A-11.01 At least two vehicles - same direction - overtaking
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	100	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		atmospheric conditions	

SaferWheels Study - CASE TSR8

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	roundabout		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	0	1	0	0
Max Severity	-	Serious	-	Not injured	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Right light
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	Unknown	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	-
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR10

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Sunday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Unknown	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	0	0	0	1
Max Severity	-	Slight	-	-	-	-

Collision Scenario		
DaCoTA accident type:	231	Turning of accident - following veh. behind right turning veh.
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	100	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Unknown	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR11

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR12

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Unknown	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	652	Longitudinal Traffic - parallel driving during overtaking - in same direction
CADAS accident type 1:	A-11.01	A-11.01 At least two vehicles - same direction - overtaking
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	80	**Vertical geometry at location:**	Up slight
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Damp	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR13

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Industrial	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	roundabout		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	352	crossing - turning priority road and veh. from the right
CADAS accident type 1:	A-12.16	A-12.16 At least two vehicles - different roads - turning left (right) into traffic from the right (left) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	60	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Multiple, comment	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR14

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	0	0	1	0
Max Severity	-	Slight	-	-	-	-

Collision Scenario		
DaCoTA accident type:	652	Longitudinal Traffic - parallel driving during overtaking - in same direction
CADAS accident type 1:	A-11.01	A-11.01 At least two vehicles - same direction - overtaking
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR15

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	399	crossing - others
CADAS accident type 1:	A-12.18	A-12.18 At least two vehicles - different roads - turning into traffic - others
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	0	**Special lane type:**	No
Road barrier present?	0	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	0	**Signage contributed to accident?**	No
Road surface defects:	0	**Road surface contaminants?**	0
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study – CASE TSR16

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	721	Others - veh. turning around and traffic from behind
CADAS accident type 1:	A-12.02	A-12.02 At least two vehicles - turning - same road - same direction - U-turn in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	60	**Vertical geometry at location:**	Unknown
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR17

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	roundabout		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	252	Turning of accident - two veh. turning right
CADAS accident type 1:	AA-12.51	AA-12.51 At least two vehicles - turning - same road - same direction - not specified
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Left
Speed Limit (km/h):	80	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR18

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	Other		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	60	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Damp	**Signage contributed to accident?**	No
Road surface defects:	bitumen patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR19

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	roundabout		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	371	crossing - crossing bicycle from the right side
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	100	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Damp	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		atmospheric conditions	

SaferWheels Study - CASE TSR20

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.14	A-12.14 At least two vehicles - different roads - turning right (left) - head on collision
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	-	**Special lane type:**	No
Road barrier present?	-	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	-	**Signage contributed to accident?**	No
Road surface defects:	-	**Road surface contaminants?**	-
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR21

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	-	-	-	-

Collision Scenario		
DaCoTA accident type:	652	Longitudinal Traffic - parallel driving during overtaking - in same direction
CADAS accident type 1:	A-11.01	A-11.01 At least two vehicles - same direction - overtaking
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up slight
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR22

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Saturday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Other	
Year:	2015		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	152	Driving accident- gradient and right turn
CADAS accident type 1:	A-11.08	A-11.08 At least two vehicles - opposite direction no turning - others
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Darkness
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	80	**Vertical geometry at location:**	Down
Road width (m):	7.8	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR23

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Sunday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Other	
Year:	2015		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	2	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	80	**Vertical geometry at location:**	Level
Road width (m):	9.24	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE TSR24

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Saturday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Other	
Year:	2015		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	152	Driving accident- gradient and right turn
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	80	**Vertical geometry at location:**	Down
Road width (m):	5	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Other
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR25

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Tuesday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Other	
Year:	2015		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	172	Driving accident- bottleneck and right turn
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Twilight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Right light
Speed Limit (km/h):	80	**Vertical geometry at location:**	Up
Road width (m):	Unknown	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	Ye
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Other	
- Main cause of sight restrictions		atmospheric conditions	

SaferWheels Study - CASE TSR26

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Fatal	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	512	Resting Traffic - evading veh. and following parking veh. on the left
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.7	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR27

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Industrial	
Year:	2015		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	132	Driving accident- non-straight street, bending to the right
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	Unknown	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR28

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Sunday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Other	
Year:	2015		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Fatal	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	601	Longitudinal traffic ? veh. and follower 1st lane
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	80	**Vertical geometry at location:**	Up slight
Road width (m):	6.2	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR29

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		Unknown	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	A-10.06	A-10.06 Single vehicle accident - Leaving straight road - either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	9.2	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Multiple, comment	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR30

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Sunday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	Light	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Left sharp
Speed Limit (km/h):	60	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Damp	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Other	

SaferWheels Study - CASE TSR31

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	243	Turning of accident - right turning veh. and cyclist from bicycle lane in same direction
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Yes	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		atmospheric conditions	

SaferWheels Study - CASE TSR32

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	10.5	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR33

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Other
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Not applicable	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Unknown	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR34

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Other	
Year:	2017		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	224	Turning of accident - left turning veh. and cyclist from bicycle lane in opposite direction
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	Light	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	Other

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE TSR35

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	2	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	652	Longitudinal Traffic - parallel driving during overtaking - in same direction
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	A-10.08	A-10.08 Single vehicle accidents on the road
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	60	**Vertical geometry at location:**	Level
Road width (m):	6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR36

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	101	Driving accident- left turn
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	Unknown

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	110	**Vertical geometry at location:**	Level
Road width (m):	12.7	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	Ye
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		vegetation, embankment	

SaferWheels Study - CASE TSR37

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Saturday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	652	Longitudinal Traffic - parallel driving during overtaking - in same direction
CADAS accident type 1:	A-11.01	A-11.01 At least two vehicles - same direction - overtaking
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Left
Speed Limit (km/h):	60	**Vertical geometry at location:**	Down slight
Road width (m):	Unknown	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR38

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Unknown	-	-	-

Collision Scenario		
DaCoTA accident type:	721	Others - veh. turning around and traffic from behind
CADAS accident type 1:	A-12.02	A-12.02 At least two vehicles - turning - same road - same direction - U-turn in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	11	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Other	

SaferWheels Study - CASE TSR39

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.65	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE TSR40

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Slight	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	183	Driving accident- bumpy road, straight road
CADAS accident type 1:	A-10.05	A-10.05 Single vehicle accidents with obstacles - others
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	potholes	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR41

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Thursday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	102	Driving accident- right turn
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	A-11.06	A-11.06 At least two vehicles - head on collision in general
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	Unknown

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	80	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	Other
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		vegetation, embankment	

SaferWheels Study - CASE TSR42

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Slight	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	623	Longitudinal Traffic - veh. waiting mendatory and follower before intersection or traffic light
CADAS accident type 1:	A-10.99	A-10.99 Single vehicle accidents - unknown
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	110	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR43

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	8.3	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Other	

SaferWheels Study - CASE TSR44

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Sunday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	Unknown

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	100	**Vertical geometry at location:**	Level
Road width (m):	6.2	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vegetation, embankment	

SaferWheels Study - CASE TSR45

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Thursday		**Area classification:**		Rural	
Season:	Summer		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Unknown	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	Unknown

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	100	**Vertical geometry at location:**	Up slight
Road width (m):	5.2	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR46

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	401	Pedestrian crossing from left onto roadway without obstacle
CADAS accident type 1:	A-8.01	A-8.01 Pedestrian crossing street - no turning of vehicle - outside a junction
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	Unknown	**Strong wind:**	Unknown

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	80	**Vertical geometry at location:**	Down slight
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	Other	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR47

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	00:00-04:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		Yes	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Fatal	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	681	Longitudinal Traffic - encountering vehicles on roadway
CADAS accident type 1:	A-11.06	A-11.06 At least two vehicles - head on collision in general
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Darkness
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	110	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	construction zone
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	Ye
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR48

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	1	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	A-9.01	A-9.01 Hitting parked vehicles right (left) side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	110	**Vertical geometry at location:**	Down slight
Road width (m):	12	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR49

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Monday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	102	Driving accident- right turn
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Right light
Speed Limit (km/h):	80	**Vertical geometry at location:**	Down slight
Road width (m):	10	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR50

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	United Kingdom		
Day of the week:	Thursday		**Area classification:**	Urban		
Season:	Winter		**Accident environment:**	Other		
Year:	2015		**Animal involvement?**	No		
Time band:	17:00-19:59		**Alcohol involvement?**	No		
Junction type:	roundabout		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	0	1	0	0
Max Severity	-	Fatal	-	Not injured	-	-

Collision Scenario		
DaCoTA accident type:	232	Turning of accident - following veh. besides right turning veh.
CADAS accident type 1:	A-12.03	A-12.03 At least two vehicles - turning - same road - same direction - turning right (left)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	Unknown	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	construction zone
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Multiple, comment	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR51

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Serious	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	A-10.06	A-10.06 Single vehicle accident - Leaving straight road - either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6.4	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR52

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	303	crossing - veh. with right of way from left and turning right
CADAS accident type 1:	A-12.13	A-12.13 At least two vehicles - different roads - turning right (left) in front of vehicle from the left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	Unknown

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	80	**Vertical geometry at location:**	Level
Road width (m):	6.6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		urban furniture	

SaferWheels Study - CASE TSR53

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Monday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	151	Driving accident- gradient and left turn
CADAS accident type 1:	A-10.08	A-10.08 Single vehicle accidents on the road
CADAS accident type 2:	A-11.06	A-11.06 At least two vehicles - head on collision in general
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	Unknown

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	7	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Multiple, comment	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Other	

SaferWheels Study - CASE TSR54

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	United Kingdom		
Day of the week:	Thursday		**Area classification:**	Urban		
Season:	Winter		**Accident environment:**	Residential		
Year:	2015		**Animal involvement?**	No		
Time band:	05:00-08:59		**Alcohol involvement?**	No		
Junction type:	crossroads		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	1	0	0
Max Severity	Fatal	-	-	Not injured	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Heavy	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	Unknown

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	6	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		walls / dwellings	

SaferWheels Study - CASE TSR55

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	roundabout		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	1	0	0
Max Severity	Fatal	-	Not injured	Not injured	-	-

Collision Scenario		
DaCoTA accident type:	611	Longitudinal Traffic - congestion and follower 1st lane
CADAS accident type 1:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 2:	A-11.06	A-11.06 At least two vehicles - head on collision in general
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.4	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR56

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Serious	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	80	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR57

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	00:00-04:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		Yes	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	151	Driving accident- gradient and left turn
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Darkness
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	Unknown

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up slight
Road width (m):	6.5	**Bend direction at location:**	Bend left
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	concrete	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Damp	**Signage contributed to accident?**	No
Road surface defects:	bitumen patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR58

Short Summary (not restricted)

Overview Details						
Investigation type:	Retrospective		**Country of investigation:**		United Kingdom	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Slight	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	303	crossing - veh. with right of way from left and turning right
CADAS accident type 1:	A-12.13	A-12.13 At least two vehicles - different roads - turning right (left) in front of vehicle from the left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		urban furniture	

SaferWheels Study - CASE TSR59

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Slight	-	-	-

Collision Scenario		
DaCoTA accident type:	631	Longitudinal Traffic - lane change to the left because of veh. ahead and follower
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	Unknown

Road Characteristics (Primary road)			
Road Type:	Principal arterial	**Horizontal geometry at location:**	Right light
Speed Limit (km/h):	110	**Vertical geometry at location:**	Down slight
Road width (m):	9.6	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE TSR60

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Tuesday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Other	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		Yes	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Fatal	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	373	crossing - crossing bicycle parallel
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	Unknown

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Right light
Speed Limit (km/h):	80	**Vertical geometry at location:**	Level
Road width (m):	7.5	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR61

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Friday		**Area classification:**		Rural	
Season:	Autumn		**Accident environment:**		Other	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	202	Turning of accident - following veh. besides left turning veh.
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	Unknown

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	100	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Unknown	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE TSR62

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	United Kingdom		
Day of the week:	Monday		**Area classification:**	Urban		
Season:	Winter		**Accident environment:**	Other		
Year:	2015		**Animal involvement?**	No		
Time band:	13:00-16:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	2	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	612	Longitudinal Traffic - congestion and follower 2nd lane
CADAS accident type 1:	A-11.04	A-11.04 At least two vehicles - same direction - side collision
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	110	**Vertical geometry at location:**	Level
Road width (m):	9.2	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	Ye
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study – CASE TSR63

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Saturday		**Area classification:**		Rural	
Season:	Spring		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	131	Driving accident- non-straight street, bending to the left
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	A-11.06	A-11.06 At least two vehicles - head on collision in general
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	100	**Vertical geometry at location:**	Up
Road width (m):	6.8	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		vegetation, embankment	

SaferWheels Study - CASE TSR64

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Other	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Serious	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	652	Longitudinal Traffic - parallel driving during overtaking - in same direction
CADAS accident type 1:	A-10.08	A-10.08 Single vehicle accidents on the road
CADAS accident type 2:	A-11.01	A-11.01 At least two vehicles - same direction - overtaking
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	Light	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	9.8	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	Damp	**Signage contributed to accident?**	No
Road surface defects:	tram rails	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR65

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Industrial	
Year:	2015		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		Yes	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	Unknown

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	8	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR66

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Fatal	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	521	Resting Traffic - evading veh. and oncoming parking veh. on the right
CADAS accident type 1:	A-10.08	A-10.08 Single vehicle accidents on the road
CADAS accident type 2:	A-11.06	A-11.06 At least two vehicles - head on collision in general
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Darkness
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7.35	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	Not applicable	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR67

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	United Kingdom		
Day of the week:	Monday		**Area classification:**	Urban		
Season:	Winter		**Accident environment:**	Residential		
Year:	2015		**Animal involvement?**	No		
Time band:	17:00-19:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	A-10.08	A-10.08 Single vehicle accidents on the road
CADAS accident type 2:	A-11.02	A-11.02 At least two vehicles - same direction - rear end collisions
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	Unknown

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	60	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR68

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Saturday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		Yes	
Junction type:	No junction		**Drug involvement?**		Yes	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	132	Driving accident- non-straight street, bending to the right
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Right
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up slight
Road width (m):	Unknown	**Bend direction at location:**	Bend right
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR69

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	05:00-08:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	141	Driving accident- straight road
CADAS accident type 1:	A-10.08	A-10.08 Single vehicle accidents on the road
CADAS accident type 2:	A-9.01	A-9.01 Hitting parked vehicles right (left) side of the road
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Right light
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up slight
Road width (m):	Unknown	**Bend direction at location:**	Bend right
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Unknown
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR70

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Fatal	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	371	crossing - crossing bicycle from the right side
CADAS accident type 1:	A-8.01	A-8.01 Pedestrian crossing street - no turning of vehicle - outside a junction
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR71

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	645	Longitudinal Traffic - lane change to the right after passing on opposite lane and follower
CADAS accident type 1:	A-11.01	A-11.01 At least two vehicles - same direction - overtaking
CADAS accident type 2:	A-11.06	A-11.06 At least two vehicles - head on collision in general
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	Unknown	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR72

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Friday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	00:00-04:59		**Alcohol involvement?**		Suspected	
Junction type:	No junction		**Drug involvement?**		Suspected	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Fatal	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	601	Longitudinal traffic ? veh. and follower 1st lane
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up slight
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	Unknown
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vegetation, embankment	

SaferWheels Study - CASE TSR73

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Saturday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		Yes	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Unknown	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	Unknown

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down slight
Road width (m):	6.25	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR74

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Monday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Industrial	
Year:	2016		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	Other		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	1	0	0
Max Severity	Fatal	-	-	Not injured	-	-

Collision Scenario		
DaCoTA accident type:	302	crossing - veh. with right of way from left and turning left
CADAS accident type 1:	A-12.17	A-12.17 At least two vehicles - different roads - turning left (right) into traffic from the left (right) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Local	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	30	**Vertical geometry at location:**	Level
Road width (m):	11	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		Other	

SaferWheels Study - CASE TSR75

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Sunday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Other	
Year:	2016		**Animal involvement?**		No	
Time band:	09:00-12:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	101	Driving accident- left turn
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Left
Speed Limit (km/h):	60	**Vertical geometry at location:**	Down slight
Road width (m):	Unknown	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	Ye
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	wet	**Signage contributed to accident?**	Unknown
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR76

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		Yes	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	301	crossing - veh. with right of way from left and going straight
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	Unknown

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Level
Road width (m):	7	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vegetation, embankment	

SaferWheels Study - CASE TSR77

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Commercial	
Year:	2015		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	slip road/ ramp		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	0	0	0	0
Max Severity	Fatal	-	-	-	-	-

Collision Scenario		
DaCoTA accident type:	101	Driving accident- left turn
CADAS accident type 1:	A-10.07	A-10.07 Single vehicle accidents in a bend - going either side of the road
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Left slight
Speed Limit (km/h):	60	**Vertical geometry at location:**	Up slight
Road width (m):	7.4	**Bend direction at location:**	Bend left
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	Yes
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR78

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Industrial	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	644	Longitudinal Traffic - lane change to the right because of mend. direction of travel and follower
CADAS accident type 1:	A-11.04	A-11.04 At least two vehicles - same direction - side collision
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Total
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	60	**Vertical geometry at location:**	Level
Road width (m):	10.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		vehicles in circulation (traffic)	

SaferWheels Study - CASE TSR79

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Unknown	
Junction type:	No junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	1	0	0	0
Max Severity	-	Fatal	Unknown	-	-	-

Collision Scenario		
DaCoTA accident type:	372	crossing - crossing bicycle from the left side
CADAS accident type 1:	A-11.03	A-11.03 At least two vehicles - same direction - entering traffic
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	Other

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Right light
Speed Limit (km/h):	60	**Vertical geometry at location:**	Level
Road width (m):	10.75	**Bend direction at location:**	Bend right
Camber:	Negative	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR80

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**	United Kingdom		
Day of the week:	Wednesday		**Area classification:**	Urban		
Season:	Summer		**Accident environment:**	Industrial		
Year:	2015		**Animal involvement?**	No		
Time band:	05:00-08:59		**Alcohol involvement?**	No		
Junction type:	No junction		**Drug involvement?**	No		
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	0	1	0	1	0	0
Max Severity	-	Fatal	-	Not injured	-	-

Collision Scenario		
DaCoTA accident type:	372	crossing - crossing bicycle from the left side
CADAS accident type 1:	A-12.12	A-12.12 At least two vehicles - crossing (no turning) - different roads
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Left
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up
Road width (m):	7.6	**Bend direction at location:**	Bend left
Camber:	Negative	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	Multiple, comment	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR81

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Industrial	
Year:	2015		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		No	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Unknown	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Secondary arterial	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	60	**Vertical geometry at location:**	Up
Road width (m):	Unknown	**Bend direction at location:**	Not Applicable
Camber:	Unknown	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		Yes	
- Main cause of sight restrictions		urban furniture	

SaferWheels Study - CASE TSR82

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Wednesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		Unknown	
Junction type:	T-junction		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Middle
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up slight
Road width (m):	7.3	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR83

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Autumn		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	13:00-16:59		**Alcohol involvement?**		No	
Junction type:	crossroads		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	322	crossing - veh. with right of way from right and turning left
CADAS accident type 1:	A-12.16	A-12.16 At least two vehicles - different roads - turning left (right) into traffic from the right (left) side
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	Unknown

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up slight
Road width (m):	7.5	**Bend direction at location:**	Not Applicable
Camber:	Other	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR84

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Saturday		**Area classification:**		Urban	
Season:	Winter		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		Suspected	
Junction type:	T-junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Slight	-	-	-

Collision Scenario		
DaCoTA accident type:	201	Turning of accident - following veh. behind left turning veh.
CADAS accident type 1:	A-12.04	A-12.04 At least two vehicles - turning - same road - same direction - turning left (right)
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	Unknown

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Down
Road width (m):	6.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR85

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Tuesday		**Area classification:**		Urban	
Season:	Spring		**Accident environment:**		Residential	
Year:	2016		**Animal involvement?**		No	
Time band:	20:00-23:59		**Alcohol involvement?**		No	
Junction type:	No junction		**Drug involvement?**		No	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Fatal	-	Not injured	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Electric light
Snowfall:	No	**Cloud cover:**	Unknown
Fog/Mist:	No	**Strong wind:**	No

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Straight
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up slight
Road width (m):	6.5	**Bend direction at location:**	Not Applicable
Camber:	None	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	None	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

SaferWheels Study - CASE TSR86

Short Summary (not restricted)

Overview Details						
Investigation type:	On-scene		**Country of investigation:**		United Kingdom	
Day of the week:	Thursday		**Area classification:**		Urban	
Season:	Summer		**Accident environment:**		Residential	
Year:	2015		**Animal involvement?**		No	
Time band:	17:00-19:59		**Alcohol involvement?**		Unknown	
Junction type:	crossroads		**Drug involvement?**		Unknown	
Vehicles Involved:	PTW	Bicycle	Car	Truck	Bus	Other
	1	0	1	0	0	0
Max Severity	Serious	-	Unknown	-	-	-

Collision Scenario		
DaCoTA accident type:	211	Turning of accident - left turning veh. and oncoming traffic in lane, straight
CADAS accident type 1:	A-12.06	A-12.06 At least two vehicles - same road - opposite direction - turning left (right) in front of other vehicle
CADAS accident type 2:	N/A	Not Applicable
CADAS accident type 3:	N/A	Not Applicable

Environmental Conditions			
Rainfall:	No	**Light Condition:**	Daylight
Snowfall:	No	**Cloud cover:**	Very little
Fog/Mist:	No	**Strong wind:**	Unknown

Road Characteristics (Primary road)			
Road Type:	Collector	**Horizontal geometry at location:**	Right light
Speed Limit (km/h):	50	**Vertical geometry at location:**	Up
Road width (m):	6	**Bend direction at location:**	Bend right
Camber:	Negative	**Construction / maintenance zone?**	none
Road surface type:	asphalt	**Special lane type:**	No
Road barrier present?	No	**Barrier collided with?**	No
Road / Infrastructure Specific Contributory Factors (Primary road)			
Road surface conditions:	dry	**Signage contributed to accident?**	No
Road surface defects:	asphalt patchwork	**Road surface contaminants?**	None
Sight restrictions contributed to accident?		No	
- Main cause of sight restrictions		Not Applicable	

HOW TO OBTAIN EU PUBLICATIONS

Free publications:

- one copy:
  via EU Bookshop (http://bookshop.europa.eu);
- more than one copy or posters/maps:
  from the European Union's representations (http://ec.europa.eu/represent_en.htm);
  from the delegations in non-EU countries
  (http://eeas.europa.eu/delegations/index_en.htm);
  by contacting the Europe Direct service
  (http://europa.eu/europedirect/index_en.htm) or calling 00 800 6 7 8 9 10 11
  (freephone number from anywhere in the EU) (*).

(*) The information given is free, as are most calls (though some operators, phone boxes or hotels may charge you).

Priced publications:

- via EU Bookshop (http://bookshop.europa.eu).

Priced subscriptions:

- via one of the sales agents of the Publications Office of the European Union
  (http://publications.europa.eu/others/agents/index_en.htm)

MI-01-18-777-EN-N

ISBN 978-92-79-90392-2
doi: 10.2832/34740